



- 1) Name of Property: Verlot Ranger Station--
Office #2031.
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking north at south-facing main facade of office
- 7) Photograph Number: 05-02-2031



- 1) Name of Property: Verlot Ranger Station--
Residence #1136
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking south at main north-facing facade, structure at far left is original snow tunnel
- 7) Photograph Number: 05-02-1136



- 1) Name of Property: Verlot Ranger Station--
Residence #1136
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly at west (right) elevation
- 7) Photograph Number: 05-02-1136-2



- 1) Name of Property: Verlot Ranger Station--
Residence #1136
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking north at south-facing rear elevation
- 7) Photograph Number: 05-02-1136-3



- 1) Name of Property: Verlot Ranger Station--
Warehouse #2259
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking north at main south-facing facade of combination warehouse/automotive shop
- 7) Photograph Number: 05-02-2259



- 1) Name of Property: Verlot Ranger Station--
Gas House #2545
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southwesterly at north gable end, main east-facing facade
- 7) Photograph Number: 05-02-2545



- 1) Name of Property: Verlot Ranger Station--
Residence #1136
 - 2) City and State: Vicinity of Granite Falls, WA
 - 3) Photographer: E. G. Throop
 - 4) Date: 9/81
 - 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
 - 6) Description: Architrave detail, main entry, note routed timbers, scrolled lintel, note also original handcrafted lantern/porch light
 - 7) Photograph Number: 05-02-1136-6
-



- 1) Name of Property: Verlot Ranger Station--
Garage #1546
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking southeasterly at north gable and, west elevation, note connecting snow tunnel at right
- 7) Photograph Number: 05-02-1546



- 1) Name of Property: Verlot Ranger Station--
Timber Management Office #1137
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking north of main south-facing facade
- 7) Photograph Number: 05-02-1137



- 1) Name of Property: Verlot Ranger Station--
Residence #1136
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Detail of pine cone door knocker
- 7) Photograph Number: 05-02-1136-5



- 1) Name of Property: Verlot Ranger Station--
Residence #1136
- 2) City and State: Vicinity of Granite Falls, WA
- 3) Photographer: E. G. Throop
- 4) Date: 9/81
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Detail of tree-shaped latchplate, USDA shield-shaped lock plate
- 7) Photograph Number: 05-02-1136-4