

### #1. Woodrow Wilson High School Middletown, CT

View: Facade

```
Facing: NW
```

```
Negative on File:
Connecticut Historical Commission
Cunningham Associates 2/86
```



#2. Woodrow Wilson High School Middletown, CT

View: Facade and north elevation 1960 addition at right. Facing: SW



### #3. Woodrow Wilson High School Middletown, CT

View: Center of facade with pavilion

Facing: W



## #4. Woodrow Wilson High School Middletown, CT

View: Entrance pavilion

```
Facing: W
```

```
Negative on file:
Connecticut Historical Commission
Cunningham Associates 2/86
```



## #5. Woodrow Wilson High School Middletown, CT

View: Rear elevation (west) and Pat Kidney Field in foreground. Facing: East from Farm Hill Avenue



### #6. Woodrow Wilson High School Middletown, CT


# View: Rear of auditorium and gymnasium addition.

Facing: E



### #7. Woodrow Wilson High SChool Middletown, CT

View: West and south elevations auditorium and gymnasium addition. Note loading beam above large arched window. Facing: NE Negative on file: Connecticut Historical Commission



#8. Woodrow Wilson High School Middletown, CT

View: South elevation. Note replacement windows top floor. Facing: N



#### #9. Woodrow Wilson High School Middletown, CT

View: Rear elevation north end. Note 1960 addition on left.

```
Facing: NE
Negative on file:
Connecticut Historical Commission
Cunningham Associates 2/86
```



### #10. Woodrow Wilson High School Middletown, CT

```
View: Entrance lobby (first floor above
grade.
Facing: N
```

```
Negative on file:
Connecticut Historical Commission
Cunningham Associates 1/86
```



#### #11. Woodrow Wilson High School Middletown, CT

View: Auditorium

Facing: SE



## #12. Woodrow Wilson High School Middletown, CT

View: Interior typical classroom



#13. Woodrow Wilson High School Middletown, CT

View: Interior of typical corner classroom



#14. Woodrow Wilson High School Middletown, CT

View: Interior library - mural wall Facing: NW

Note: Glass-front wood cabinets removed from below mural.

Negative on file:

Connecticut Historical Commission Cunningham Associates 2/86



# #15. Woodrow Wilson High School Middletown, CT

```
View: Interior library - mural wall
Facing: SW
Note: Glass-front wood cabinets removed
    from below mural.
Negative on file:
        Connecticut Historical Commission
Cunningham Associates 2/86
```