



Service

POWER

WE TR OP OL TET AN

VICTORIAN LIFE

VICTORIAN LIFE

GARAGE

DETROIT

WALKER

THE CARTER CO.

THE CARTER CO.

THE CARTER CO.

CARTER CO.

Circle Motor Inn

WEST PHARMACY LAUNDRY

Test Building

54 Monument Circle, Indianapolis, IN

Photographer: Bass Photo Company

Date: between 1925 and 1929

Negative: Bass Photo Company, Indianapolis

Number 331133

Circle and Market Street elevations from
the northeast

#1 of 9



FOOTNOTES
BROADWAY NEW YORK

Cannis Shop
Home, Wash, Canada

MORROW'S

**MORROW'S
NUT
HOUSE**

**MORROW'S
NUT
HOUSE**

KIT

GARAGE

Test Building

54 Monument Circle, Indianapolis, IN

Photographer: Mary Ellen Gadski

December 8, 1982

Negative: Indianapolis Historic Preservation

Commission Office, 1821 City/County Bldg.

Circle and Market Street elevations from
the northeast

2 of 9



1. Test Building
2. 54 Monument Circle, Indianapolis, IN
3. Photographer, Wilber Montgomery
4. February 21, 1983
5. Negative: Browning Day Pollak Mullins
Dierdorf Incorporated
124 South Meridian Street
6. Circle elevation from the east

3 of 9



Way
ndies

TEST

TEST BUILDING
3-E

CONST
F. TRANCE

The American
Shoe & Canvas Co.
Manufacturers
of
High Top Canvas
Shoes
775 Broadway, N.Y.

CHRONIC JEWELRY
943 N. 19th
St. Louis, Mo.

CHRONIC JEWELRY
943 N. 19th
St. Louis, Mo.

1. Test Building
2. 54 Monument Circle, Indianapolis, IN
3. Photographer, Wilber Montgomery
4. February 21, 1983
5. Negative: Browning Day Pollak Mullins
Dierdorf Incorporated
124 South Meridian Street
6. Main entryway, Circle elevation

#4 of 9

Nat Smith MEN'S SHOPS

58



1. Test Building
2. 54 Monument Circle, Indianapolis, IN
3. Photographer, Wilber Montgomery
4. February 21, 1983
5. Negative: Browning Day Pollak Mullins
Dierdorf Incorporated
124 South Meridian
6. Typical storefront with original
configuration preserved

5 of 9




1. Test Building
2. 54 Monument Circle, Indianapolis, IN
3. Photographer, Wilber Montgomery
4. February 21, 1983
5. Negative: Browning Day Pollak Mullins
Dierdorf Incorporated
124 South Meridian Street
6. Ninth floor with frieze below and
cornice above

#6 of 9



1. Test Building
2. 54 Monument Circle, Indianapolis, IN
3. Photographer, Wilber Montgomery
4. February 21, 1983
5. Negative: Browning Day Pollak Mullins
Dierdorf Incorporated
124 South Meridian Street
6. Third floor sculptural panel of
biplane, Circle elevation

#7 of 9



Test Building

54 Monument Circle, Indianapolis, Indiana


Photographer: Wilbur Montgomery

February 21, 1983

Negative: Browning Day Pollak Mullins
Dierdorf Incorporated

View up from Fifth floor Garage showing
ramp and staggered floors.

8 of 9



M

SLOW

M

Test Building

54 Monument Circle, Indianapolis, Indiana

Photographer: Wilbur Montgomery

February 21, 1983

Negative: Browning Day Pollak Mullins

Dierdorf Incorporated

View of down ramp at Garage

#9 of 9