



George Cowles House

Farmington, CT

D. Ransom Photo, 3/81

Negative: Connecticut

Historical Commission

SOUTH PORTICO, VIEW

NORTH

Photograph 1 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 3/81

Negative: Connecticut

Historical Commission

DETAIL, PORTICO PEDI-

MENT, VIEW NORTH

Photograph 2 of 14



George Cowles House  
Farmington, CT  
D. Ransom Photo, 4/81  
Negative: Connecticut  
Historical Commission  
FACADE, VIEW WEST  
Photograph 3 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 3/81

Negative: Connecticut

Historical Commission

ENTRANCE, VIEW WEST

Photograph 4 of 14





George Cowles House

Farmington, CT


D. Ransom Photo, 3/81

Negative: Connecticut

Historical Commission

WING, VIEW SOUTHEAST

Photograph 5 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 3/81

Negative: Connecticut

Historical Commission

OUTBUILDINGS, VIEW NORTH-  
WEST

Photograph 6 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 4/81

Negative: Connecticut

Historical Commission

BARN, VIEW SOUTHWEST

Photograph 7 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 4/81

Negative: Connecticut

Historical Commission

STAIR HALL, VIEW NORTH-

WEST

Photograph 8 of 14.





George Cowles House

Farmington, CT

D. Ransom Photo, 3/81

Negative: Connecticut

Historical Commission

DOORWAY TO DRAWING ROOM,

VIEW SOUTH

Photograph 9 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 3/81

Negative: Connecticut

Historical Commission

DRAWING ROOM, VIEW SOUTH-  
EAST

Photograph 10 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 4/81

Negative: Connecticut

Historical Commission

DINING ROOM ALCOVE, VIEW

SOUTHEAST

Photograph 11 of 14



George Cowles House

Farmington, CT

D. Ransom Photo, 4/81

Negative: Connecticut

Historical Commission

BALLROOM, VIEW NORTH

Photograph 12 of 14





George Cowles House

Farmington, CT

Original photo at Connecticut  
Historical Society; negative  
of copy at CHS

WILLIAMS HOUSE, VIEW SOUTHWEST,  
BEFORE 1894

Photograph 13 of 14



George Cowles House  
Farmington, CT  
Original photo at Connecticut  
Historical Society; negative  
of copy at CHS  
HUDSON HOUSE, VIEW SOUTHWEST,  
1894  
Photograph 14 of 14

Note: This is the Hudson House & is not the  
subject of this nomination. ~~The~~ The  
picture is included to show the comparisons  
with the Cowles House