	TORIC RESOURCES INVENTORY	4 D T	FOR OFFICE USE ONLY		
	LDING AND STRUCTURES	02 125	Town No.: Site No.:		
	CONNECTICUT STATE OF CONNECTICUT STATE OF CONNECTICUT		UTM 1 8 6 7 4 7 8 0 4 6 0 5 5 8 0		
	59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT (203) 566-3005	06106	QUAD:		
ſ			DISTRICT IF NR, SPECIFY		
<u>ا</u> ک	1. BUILDING NAME (Common)	(Historic)	S NR Actual Potential		
DENTIFICATION		Capt. Jos.	iah Cowles House		
	2. TOWN/CITY VILLAGE	CT 06470	Hartford		
	3. STREET AND NUMBER (and/or location)				
1 C	184 Marion Ave. (map 69, parcel 63-A) 1.058 acres				
III	Potter, Mary M. & David L. (vol. 324, p. 485)				
10 EI	5. USE (Present) (Historic)				
	Residential Residential				
	TO PUBLIC: X Yes No Yes X N				
	7. STYLE OF BUILDING Colonial		DATE OF CONSTRUCTION		
	8. MATERIAL(S) (Indicate use or location when appropriate)	- <del> </del>	L		
	Clapboard Asbestos Siding Brick	Other (Specify	/)		
	Wood Shingle Asphalt Siding Fieldston	•			
	Board & Batten Stucco Cobbiesto				
	Aluminum Concrete Cut stone				
	Siding Type: Type: Type:				
6	Y     Wood frame     Past and beam     balloon				
	Load bearing masonry Structural	iron or steel			
	Other (Specify)				
	10. ROOF (Type)       X Gable       Flat       Mansard       Monitor	sawtoo	th		
NO	Gambrel Shed Hip Round	<b>Other</b> (Specif	y)		
DESCRIPTION	(Material)				
	Wood Shingle Asphalt Tin Slate				
	X Asphalt shingle Built up Tile Other (Specify)				
	11. NUMBER OF STORIES       APPROXIMATE DIMENSIONS         2       31 x 20' + 20 x 20' 1-story ell				
	12. CONDITION (Structural) (Exterior)				
			ood 🔲 Fair 🗋 Deteriorated		
	13. INTEGRITY (Location)       WHEN ?       (Alterations)       IF YES, EXPLAIN         X On original site       Moved       X Yes       No       Porches removed				
	14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES         Barn       Shed       X         Other landscape features or buildings (Specify)       pool				
	Carriage Shop Garden				
	15. SURROUNDING ENVIRONMENT				
(	Open land Mood- X Residential Scattered buildings visible from site				
	Commercial Indus- Rural High building density				
	16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS The house faces north on a busy street.				
	The house faces not the on a busy stree				
			(OVER)		

=

	17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)			
DESCRIPTION (Continued)	In the 5-bay front elevation, the 12/12 windows have a 2-1-2 rhythm. The double central door has a simple molded surround. Windows have flat caps. There are corner boards, and a central brick chimney. The WPA survey photo shows central pedimented portico and Colonial Revival side porch, on the east, which have been removed. At that time windows were 6/1 and the double front door had 5-panel leaves and bull's eye glazing. The form reports, on the interior, no summer beams and scrolled step ends on the stairway, rising from right to left.			
	18. ARCHITECT BUILDER			
SIGNIFICANCE	19. HISTORICAL OR ARCHITECTURAL IMPORTANCE			
	The house is significant architecturally as a good example of the Colonial style.			
	The local association of this house with Capt Josiah Cowles (1716-1793) combined with an appraisal of its stylistic features suggests a slightly later construction date, perhaps around 1750, rather than the 1728 assigned to the building by the assessor's records. Cowles married in 1739, then, when his first wife died in 1746, he married again in 1748. His title of Captain is a military rank; he also served as a justice of the peace.			
SOURCES				
_	PHOTOGRAPHER			
рното	David Ransom 11/85			
	Southwest Y-29			
COMPILED BY	Southwest     125       Name     David Ransom       David Ransom     11/85			
MPI	ADDRESS 33 Sunrise Hill Drive West Hartford CT 06107			
õ				
20. 3	West Hartford, CT 06107			
21.	THREATS TO BUILDING OR TITE None known Highways Vandalism Developers Other			
1 1	Renewal Private Deterioration Zoning Explanation			