



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

1 of 26

panel one of historic panorama farm  
setting c. 1900  
photographer unknown

Christopher Rubright  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

2 of 26  
panel two of panorama  
c. 1900  
photographer unknown

Christopher Rubright  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

3 of 26

panel 3, historic panoramic view  
c. 1900

photographer unknown

Christopher Rubright  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

4 of 26  
South elevation

Nancy Bohon photo, 1985  
1191 Coos Bay Wagon Rd.  
Roseburg, OR 97470





Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
lookingglass vcty., Douglas County,  
Oregon

5 of 26

West elevation, showing encircling  
rain gutter, corral and loading  
chute

Nancy Bohon photo, 1985  
1191 Coos Bay Wagon Rd.  
Roseburg, OR 97470



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

6 of 26 (A)  
East elevation

Rain water collected from the gutter  
accumulated in the barrel and was piped  
to a cistern underneath the farmhouse.

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Road  
Lookingglass vcty., Douglas County,  
Oregon

6 of 26 (B)

East elevation, showing closer view  
of rain water collection system.

Christopher Rubright photo, 1985  
929 Queen Anne Ave., N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

7 of 26

Northeast elevation

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109





Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas Coutny,  
Oregon

8 of 26  
North elevation

Christopher Rubright photo, 1985  
929 Queen Anne Ave., N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos bAy Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

9 of 26

Northwest elevation

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos BAy Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

10 of 26

West elevation

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109

**West Elevation**



Wimer, James, Octagonal Barn  
1191 Coos bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

11 of 26  
Southwest elevation

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109





Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

12 of 26  
South elevation

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

13 of 26  
Cupola

Christopher Rubright photo, 1985  
929 Queen ANne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

14 of 26

Board and batten siding attached  
with square-headed nails

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

14 of 26

Corner detail, northwest corner

Christopher Rubright, photo, 1985  
929 Queen Anne Ave., N., #305  
Seattle , WA 98109





Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

16 of 26

Main door, north side

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

17 of 26

Interior, looking southwest from  
the north main doors

Christopher Rubright, photo, 1985  
929 Queen Anne Ave., N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

18 of 26

Stone footing, interior

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109




Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

19 of 26

Framing detail showing beam  
notched to accept joists

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109





Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

20 of 26

Pegged post and beams

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

21 of 26

Wall of enclosed fruit storage room

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

22 of 26

Corner detail at roof

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

23 of 26

Interior, looking northeast from  
the south main doors

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109





Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oreogn

24 of 26

Loft interior, looking west

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos BAy Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

25 of 26

Roof framing in loft

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109



Wimer, James, Octagonal Barn  
1191 Coos Bay Wagon Rd.  
Lookingglass vcty., Douglas County,  
Oregon

26 og 26

Loft interior showing hay chutes

Christopher Rubright photo, 1985  
929 Queen Anne Ave. N., #305  
Seattle, WA 98109