



Name: Linden Hall - Ricards House

Location: U.S. 13 and Road 600, Bridgeville, DE

Photographer: Richard B. Carter

Date: Dec., 1980

Location of Negative: Hall of Records, Dover, DE

Description: Facade view of house showing double verandah.

Photograph Number: 1 of 9



Name: Linden Hall - Ricards House

Location: U.S. 13 and Road 600, Bridgeville, DE

Photographer: Richard B. Carter

Date: Dec. 1980

Location of Negative: Hall of Records, Dover, DE

Description: Detail view of second floor porch.

Photograph Number: 2 of 9



Name: Linden Hall - Ricards House

Location: U.S. 13 and Road 600, Bridgeville, Delaware

Richard B. Carter


Photographer: Dec., 1980

Date:

Location of Negative: Hall of Records, Dover, DE

Description: West gable end of wood frame front section.

Photograph Number: 3 of 9



Name: Linden Hall - Ricards House

Location: U.S. 13 and Road 600, Bridgeville, DE

Photographer: Richard B. Carter

Date: Dec., 1980

Location of Negative: Hall of Records, Dover, DE

Description: View of house from northeast showing rear of front frame section at left and side view of rear brick section at right (with wood frame enclosed porch).

Photograph Number: 4 of 9





**Name:** Linden Hall - Ricards House

**Location:** U.S. 13 and Road 600, Bridgeville, DE

**Photographer:** Richard B. Carter

**Date:** Dec., 1980

**Location of Negative:** Hall of Records, Dover, DE

**Description:** Northwest gable end of original brick section showing later applied Victorian trim.

**Photograph Number:**

5 of 9



**Name:** Linden Hall - Ricards House

**Location:** U.S. 13 and Road 600, Bridgeville, Delaware

**Photographer:** Richard B. Carter


**Date:** Dec., 1980

**Location of Negative:** Hall of Records, Dover, DE

**Description:** View of fireplace in Ca. 1860 addition.

**Photograph Number:**

6 of 9



Name: Linden Hall - Ricards House

Location: U.S. 13 and Road 600, Bridgeville, DE

Photographer: Richard B. Carter

Date: Dec., 1980

Location of Negative: Hall of Records, Dover, DE

Description: View of framing members of 1820's wood frame section (note plate and stud numbered with Roman numerals in center).

Photograph Number: 7 of 9



Name: Linden Hall - Ricards House

Location: U.S. 13 and Road 600, Bridgeville, DE

Photographer: Richard B. Carter

Date: Dec., 1980

Location of Negative: Hall of Records, Dover, DE

Description: Detail of arched brick fireplace support  
in basement of original brick section.

Photograph Number: 8 of 9





Linden Hall - Ricards House

Name:

Location: U.S. 13 and Road 600, Bridgeville, DE

Photographer: Richard B. Carter

Date: Dec., 1980

Location of Negative: Hall of Records, Dover, DE

Description: View of doorway between second floor room in original brick section and that in front wood frame section.

Photograph Number:

9 of 9