

Form No. 10-301a (Pev. 10-7')

> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

| FO | RNPSU | SEONLY | 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1 |
|-----|---------|------------|--|
| | | | |
| 0 | COLIVED | DCT 8 1975 | |
| Inc | CEIVED | 001 0 19/3 | and the second |
| 1 | | | kana aka na s |
| | | | |
| DA | TE ENTE | RED NOV 2 | 0 1975 |

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES __ ENCLOSE WITH PHOTOGRAPH

| 1 NAME | |
|---|--------------------------------|
| HISTORIC | |
| Thomas Lyman House | |
| AND/OR COMMON | |
| 2 LOCATION | |
| CITY, TOWN | COUNTY STATE |
| Durham | Connecticut |
| 3 PHOTO REFERENCE | |
| PHOTO CREDIT S.J. Raiche | DATE OF PHOTO August 12, 1974. |
| NEGATIVE FILED AT | • |
| Connecticut Historical Commission | |
| 4 IDENTIFICATION | · · |
| DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET | r РНОТО NO. 1 |


main elevation, main house block. This section exists in unaltered state. Note typical Connecticut treatment of main entrance and portico, and retention of overhang in this later 18th century house. Note use of perfectly cut granite foundation blocks. Main elevation of ell(right of view) is intact. View northwest.



Form No. 10-301a (Pev. 10-7.)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM



| NAME | 10 | | |
|--------------------------|----------------|--------------------------------|-------------|
| HISTORIC | N | | |
| Thomas Lyman House | | | |
| AND/OR COMMON | | - | |
| LOCATION | | | |
| CITY, TOWN | VICINITY OF | COUNTY | STATE |
| Durham | · | | Connecticut |
| PHOTO REFERENCE | | | |
| PHOTO CREDIT S.J. Raiche | | DATE OF PHOTO August 12, 1974. | |
| NEGATIVE FILED AT | | | |
| , | cal Commission | | |


DESCRIBE VIEW. DIRECTION. ETC. IF DISTRICT. GIVE BUILDING NAME & STREET Side ell., view southwest, somewhat altered from original by present owner 2 but retaining original feeling. Stone walls in foreground are recent.



| Form | No. | 10-301a | |
|-------|-----|---------|--|
| (Pev. | 10- | 7.4) | |

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM



SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES ENCLOSE WITH PHOTOGRAPH

| 1 NAME | | | |
|---|---|--|-----------------------------------|
| HISTORIC | | | • |
| Thomas Lyman | House | | |
| AND/OR COMMON | | | |
| 2 LOCATION | | | |
| ĊITY, TOWN | VICINITY OF | COUNTY | STATE |
| Durham | | | Connecticut |
| 3 PHOTO REFERENC | Æ | | |
| PHOTO CREDIT S.J. Raiche | | DATE OF PHOTO | August 12, 1974. |
| NEGATIVE FILED AT | | | |
| Connecticut | Historical Commission | | |
| 4 IDENTIFICATION | | , | |
| DESCRIBE VIEW, DIRECTION, ETC. IF D | ISTRICT, GIVE BUILDING NAME & STREE | т | PHOTO NO. 3 |
| rear elevation, main hous house has been closed, an view northeast. | se block and side ell. And other modifications h | . doorway in the gr nave been made in r | ound floor of main ear of ell. |