



Small window in the gable of the front facade.

White sign mounted on the second floor of the front facade.

Window on the second floor of the front facade.

Window on the second floor of the front facade.

Window on the first floor of the front facade.

Window on the first floor of the front facade.

Window on the second floor of the side facade.

Window on the second floor of the side facade.

Window on the second floor of the side facade.

Window on the second floor of the side facade.

Window on the second floor of the side facade.

Window on the first floor of the side facade.

Window on the first floor of the side facade.

Window on the first floor of the side facade.

Window on the first floor of the side facade.

Window on the first floor of the side facade.

#1 Old Counting House

South Berwick, Maine

View towards the East

Form No. 10-301a  
(Rev. 10-73)

UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY  
JUL 17 1975  
RECEIVED  
DATE ENTERED OCT 10 1975

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

Counting House

AND/OR COMMON

**2 LOCATION**

CITY, TOWN

South Berwick

VICINITY OF

COUNTY

York

STATE

Maine

**3 PHOTO REFERENCE**

PHOTO CREDIT

Earle G. Shettleworth, Jr.

DATE OF PHOTO

1975

NEGATIVE FILED AT

Maine Historic Preservation Commission

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

View from the west

R. D. Kelly Oct. 1973