

Name: WARREN'S MILL

SUSSEX COUNTY

Location: near Millsboro, Delaware

Photographer: Joan M. Norton

Date: January, 1978 Location of Negative:

Bureau of Arch. & Historic Pres. DHCA, Dover, Del.

Description:

3/4 view of Warren's Mill from south.

Photograph Number: 1 7 6 MAR 15 1978



Location: Sussex County near Millsboro, Delaware

Photographer: Joan M. Norton

Date: January 1978

Location of Negatives Bur. of Arch. & Hist. Preservation DHCA, Dover, Delaware

Description:

3/4 view of Warren's Mill from west.

Photograph Number: 2 28

MAR 1 1 1978



Name: WARREN'S MILL

Location: near Millsboro, Delaware Success County

Photographer: Joan M. Norton

Date: January 1978

Location of Negatives Bur. of Arch. & Hist. Preservation DHCA, Dover, Delaware

Description:

Rear view of Warren's Mill from northeast.

Photograph Number: 3 8

MAR 1 5 1978



## Names WARREN'S MILL

Locations near Millsboro, Delaware Sussex Conty

Photographer: Joan M. Norton

Date: January 1978

Location of Negatives

Bur. of Arch. & Hist. Preservation DHCA, Dover, Delaware. Description:

Detail of roof framing in Warren's Mill.

Photograph Number:

4 8 8 MAR 1 5 1978



## Names WARREN'S MILL

Locations near Millsboro, Delaware Sussex Courty
Photographers Joan M. Norton

Date: January, 1978
Location of Negatives Bur. of Arch. & Hist. Preservation,
DHCA, Dover, Delaware.

Description:

Detail of mill race with part of turbine.

Photograph Numbers 5 8

MAR 15 1978





Locations near Millsboro, Delaware Syssex County

Photographer: Joan M. Norton

Date: January, 1978

Location of Negatives Bur. of Arch. & Hist. Preservation: DHCA, Dover, Delaware.

Description:

Facade view of shed from southwest.

Photograph Numbers



MAR 15 1978



Location: near Millsboro, Delaware

Joan M. Norton

Date: January, 1978

Photographer:

Location of Negative: Bur. of Arch. & Hist. Preservation; DHCA, Dover, Delaware.

Description:

3/4 view of shed from south.

Photograph Number: 7

MAR 15 1978



Name: WARREN'S MILL

Location: Near Millsboro, Delaware Sasse Carry

Photographer: Joan M. Norton Date: January, 1978

Location of Negative: Bur. of Arch. & Hist. Preservation; DHCA, Dover, Delaware.

Description:

3/4 view of stable from south.

Photograph Number: 8 a 8

MAR 151978