#### United States Department of the Interior Heritage Conservation and Recreation Service

#### National Register of Historic Places Inventory—Nomination Form



See instructions in *How to Complete National Register Forms* Type all entries—complete applicable sections

### 1. Name

historic Pacific Desk Building

and/or common Andreas Romero Building

#### 2. Location

 street & number
 213-215
 Gold Avenue S.W.
 \_\_\_\_\_\_\_\_\_\_not for publication

 city, town
 Albuquerque
 \_\_\_\_\_\_\_\_\_vicinity of
 congressional district
 #1

35

code

state

<u>...</u>

New Mexico

New Mexico

in process

being considered

## 3. Classification

Category	Ownership
district	public
X building(s)	<u>x</u> private
structure	both
site	<b>Public Acquisition</b>

object

#### Status X occupied unoccupied work in progress Accessible yes: restricted X yes: unrestricted no

county

	Present U
	agricu
	comm
5	educa
	enterta
	goveri
1	indust

military

Bernalillo

ent Use	
griculture	museum
ommercial	park
ducational	private residence
ntertainment	religious
overnment	scientific
dustrial	transportation

 transportation
 other:

code 001

### 4. Owner of Property

name Thomas L. Popejoy, Jr.

street & number 1905 Avenida Las Campanas N.W.

Albuquerque	vicinity of	state	New	Mexico	87107
ation of Leg	gal Description				
jistry of deeds, etc.	Bernalillo County Clerk's	s Office			
r	505 Central Avenue N.W.				
	Albuquerque	state	New	v Mexico	-
resentation	n in Existing Surve	eys 🔤			
Register of Cultur	ral Properties this property been	determined e	legible	e? <u>X</u> y	es no
25, 1980	fec	leral <u>X</u> sta	nte	county	local
) )	istry of deeds, etc. <b>resentation</b> Register of Cultur	505 Central Avenue N.W. Albuquerque resentation in Existing Surve Register of Cultural Properties this property been	Albuquerque state resentation in Existing Surveys Register of Cultural Properties this property been determined e	pistry of deeds, etc. Bernalillo County Clerk's Office 505 Central Avenue N.W. Albuquerque state New resentation in Existing Surveys Register of Cultural Propertiess this property been determined elegible	Albuquerque state New Mexico <b>resentation in Existing Surveys</b> Register of Cultural Properties this property been determined elegible? X ye

city, town Albuquerque

state New Mexico

## 7. Description

Condition		Check one
excellent	deteriorated	<u>x</u> unaltered
good	ruins	altered
x fair	unexposed	

Check one \_\_\_\_ original site \_\_\_\_ moved date \_\_

#### Describe the present and original (if known) physical appearance

Among the older buildings of downtown Albuquerque, New Mexico, the Pacific Desk Building is one of the handful which has escaped modernizing or extensive remodeling. A fairly straightforward brick commercial building erected in 1914, it is distinguished by its first-floor cast-iron facade (one of only two remaining in the CBD), its handsome second-story fenestration, and the fine stamped metal ceiling of its open interior.

The Pacific Desk Building is 50 feet wide by 142 feet long, facing south. Both sides of the building were originally party-walled with adjoining structures; the structure to the west has since been demolished. On the street facade, the first floor has full-width display windows supported by the cast metal framework from a local foundry. The four columns have simple circular ornaments and a stylized flower design on the capital. The centered entrance is set back about five feet from the facade in a recessed bay. On the west side, a glass door with a transom above leads to the second story.

The second story has an evenly spaced band of eight windows; cast iron hoods are placed over the three windows at either end. In the center, the coped parapet rises about a foot over the pair of centered windows to emphasize the entry; a plaque, now blank, presumably once displayed the building name. The 1/1 wood sash windows, set under molded concrete lintels and sills, are framed at the sides by a row of stepped-in bricks. A concrete molding connects all the windows at the bottom of the lintel. On the east and west sides, the second floor has a row of plainly framed wood windows. On the alley facade, windows on both floors are set under arched frames, probably segmental brick with a stucco coating.

The open first-story interior space retains the original hardwood floors, as well as the unusually elaborate cast metal ceiling. A row of cast iron columns connect with a heavy molding in the center of the space to support the second-story and roof. This molding, also sheathed in stamped metal, vees out to connect with the exterior cast iron supports framing the entrance, creating a dramatic and effective pattern.

The second story interior space, originally open, now has some removable partitions added during World War II, when the Soil and Water Conservation Service occupied the floor. Since 1954, the second floor has been used only for storage, and is in need of considerable rehabilitation if it is to be put in use again. A forty-foot long basement runs the full width of the building.

The Pacific Desk Building is located on a block of continuous buildings of similar age; it is the only building on the south side of Gold to have escaped remodelling. Across the street at the corner of Gold and 3rd is the B Building, an 1881 adobe commercial structure which has also retained many early features. Gold Avenue, appropriately, was the financial and government street in the early years of the city; now most of the larger buildings to the east have been demolished, and only this block and the next block to the west retain some of the early atmosphere of railroad-era Albuquerque.

### 8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799 1800–1899 1900–	Areas of Significance—C archeology-prehistoric archeology-historic agriculture x architecture art commerce communications	• •
Specific dates	1914	Builder/Architect

A 18 4

#### Statement of Significance (in one paragraph)

The Pacific Desk Building is important primarily as one of the very few examples of substantially unaltered early 20th-century architecture in downtown Albuquerque, New Mexico. Built in 1914, it reflects the taste of the times in its cast-iron store front, brickwork, and fine interior stamped metal ceiling. Built in the era just before the rediscovery of native Southwestern architectural forms, it typifies the simplified adaptation of eastern forms seen in most architecture of the period. As one of the earliest automobile sales rooms in Albuquerque, it also reflects the 20th century transformation of the city from a railroad town to a car town.

The Pacific Desk Building was erected for Andreas Romero, who owned a butcher shop down the street at 211 Gold when he acquired the property in 1907. When the building was built, a party wall agreement called for "rubble stonework of good sound mountain granite laid in good lime and sand" for the foundation, and walls of "local sand-mould brick laid in good lime mortar in regular courses and regularly bonded." The first tenant, for two years, was the Faber Furniture Store, but by 1918 the building had become the home of the Albuquerque Motor Company and Barber Wholesale Automobiles. By 1922, it was rented to Livingston Furniture, who continued as tenants until 1928.

Andreas Romero died in 1925, willing the property to his wife Eduvigen. In 1927. she transferred title to her daughter Catrina Romero de Sanchez who held title until 1942, when it was purchased by Charles and Helen Hoit, the proprietors of the Pacific Desk Company. Between 1928 and 1943, when Pacific Desk Company opened shop in the building, it continued to be leased to furniture companies.

Charles Hoit's business and property passed to his daughter and son-in-law, Thelma and R.G. Lee, Jr., who have continued to run Pacific Desk Company, an office furniture sales company, in the building. The building has now been sold to Thomas L. Popejoy, Jr., a local attorney interested in historic preservation, who plans rehabilitation for legal offices. Happily, the transfer of ownership comes at a time when rehabilitation can prevent serious structural problems with this little-altered building.

## 9. Major Bibliographical References

Albuquerque City Directories Bernalillo County Records Conversations with R.G. Lee, Jr. Unpublished paper by George E. Bennett in Historic Landmarks Survey files.

#### **10. Geographical Data**

## ACREAGE NOT VERIFIED

Acreage of nominated property <u>\_\_\_16\_acre\_\_\_\_</u> Quadrangle name <u>Albuquerque W</u>est, New Mexico

## UMT References A 113 3 4 3 3 3 4 3

Zone	Easting	Northing
c 🛄		
E		
G		

# ITM NOT VERIELED ale 1:24,000



#### Verbal boundary description and justification

Lots 19 and 20 of Block 16 of the Original Townsite, City of Albuquerque; the lots together measure 50' x 142'. This boundary includes the land occupied by the building.

List all states and counties for properties overlapping state or county boundaries

state	code	county		code
state	code	county	· · · · · · · · · · · · · · · · · · ·	code
11. Form Prepa	ared By			
name/title Susan Dewitt, Coo	ordinator			
organization Historic Landmar	<u>ks Survey of</u>	Albuquerque	date <sub>May 21</sub> , 19	80
street & number 419 Central A	venue N.W.		telephone (505) 7	66–4720
city or town Albuquerque			state New Mexic	0
12. State Histo	ric Pres	ervatio	n Officer C	ertification
The evaluated significance of this p	property within the	state is: X_local		
As the designated State Historic Pr 665), I hereby nominate this proper according to the criteria and proced	ty for inclusion in	the National Regi	ster and certify that it h	as been evaluated
State Historic Preservation Officer		Thmas	w rel_	
title Ste Hortme	Promut	- Officer	L date	8-1-80
For ACRE use any				
(Reg Carlos				

÷