



09-23

Bellows Falls Island Multiple
Resource Area

Rockingham, Vermont

Credit: Hugh H. Henry

Date: April 1988

Negative filed at Vermont Division
for Historic Preservation

Description: Bellows Falls
Co-operative Creamery (building
#8), east facade. View looking
west.

Photograph 23



88-454

Bellows Falls Island Multiple
Resource Area
Rockingham, Vermont

Credit: Hugh H. Henry

Date: May 1988

Negative filed at Vermont Division
for Historic Preservation

Description: Bellows Falls
Co-operative Creamery complex
(buildings #8A and 8, from left),
south and east facades. View
looking northwest.

Photograph 24

SEP 26 1988



88A-37

Bellows Falls Island Multiple
Resource Area
Rockingham, Vermont

Credit: Hugh H. Henry

Date: May 1988

Negative filed at Vermont Division
for Historic Preservation

Description: Bellows Falls
Co-operative Creamery (building
#8), north and west facades. View
looking south.

Photograph 25

SEP 26 1988

25



Bellows Falls Island Multiple
Resource Area
Rockingham, Vermont

Credit: Hugh H. Henry

Date: April 1988

Negative filed at Vermont Division
for Historic Preservation

Description: Bellows Falls
Co-operative Creamery (building
#8), south facade. View looking
north.

Photograph 26

88A-37