

Miriam Gaitskill June 1977

AUG 2 1978

Photo 1. Main facade viewed from west.



Loudoun Hall Paris Bourbon County Kentucky

Mirian Gaitskill June 1977

AUG 2 1978

Photo 2. Earliest section viewed from southeast.



Miriam Gaitskill June 1977

AUG 2 1978

Photo 3. Detail of central entrance, viewed from west.



Miriam Gaitskill June 1977

AUG 2 1978

Photo 4. Detail of portico's coffered ceiling.



Miriam Gaitskill June 1977

AUG 2 1978

Photo 5. Main entrance. Note wallpaper 'molding' in upper left.



Miriam Gaitskill June 1977

AUG 2 1978

Photo 6. Open stairway in central hall; note original OCT 3 1 1977 wallpaper.



Miriam Gaitskill June 1977

AUG 2 1978

Photo 7. Mantel in west parlor.



Miriam Gaitskill June 1977 AUG 2 1978

OCT 31 1977

Photo 8. Door leading from south parlor into bedroom. Note shouldered architrave and high baseboard.



Miriam Gaitskill June 1977 AUG 2 1978

OCT 31 1977

Photo 9. Detail of federal mantel and chair-rail in earlier brick section.



PROPERTY OF THE MATICINAL REGISTER

Photo 10 gl

Loudo: Hall (Grimes House)
Bourbon County
Kentucky
JUN 1 2 1978

Dan Kidd, Kentucky Heritage Commission March, 1978

AUG 2 1978

1909 Frame dwelling identified as B on site location map.
Photgrapher facing northeast



Photo 11 9 Loudoun Hall (Grimes House) Bourbon County.

Kentucky JUN 12 1978

Dan Kidd. Kentucky Heritage Commission March. 1978 Buildings D. E. and F on site location map. Photographer facing northwest.