



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

<b>FOR NPS USE ONLY</b>	
RECEIVED	JAN 16 1976
DATE ENTERED	MAY 28 1976

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

General William O. Butler House

AND/OR COMMON

Same

**2 LOCATION**

CITY, TOWN

Carrollton

\_\_\_ VICINITY OF

COUNTY

Carroll

STATE

Kentucky

**3 PHOTO REFERENCE**

PHOTO CREDIT Public Information Frankfort, Kentucky

DATE OF PHOTO November 1975

NEGATIVE FILED AT

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

Photo taken from the south showing the facade which faces the road.

PHOTO NO.

1 of 5



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY	
RECEIVED	JAN 16 1976
DATE ENTERED	MAY 28 1976

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

General William O. Butler House

AND/OR COMMON

Same

**2 LOCATION**

CITY, TOWN

Carrollton

\_\_\_ VICINITY OF

COUNTY

Carroll

STATE

Kentucky

**3 PHOTO REFERENCE**

PHOTO CREDIT Public Information Frankfort, Kentucky

DATE OF PHOTO November 1975

NEGATIVE FILED AT

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Photo taken from the south showing the detail of the Palladian framework.

PHOTO NO.

245



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED JAN 16 1976

DATE ENTERED MAY 28 1976

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

General William O. Butler House

AND/OR COMMON

Same

**2 LOCATION**

CITY, TOWN

Carrollton

\_\_\_ VICINITY OF

COUNTY

Carroll

STATE

Kentucky

**3 PHOTO REFERENCE**

PHOTO CREDIT Public Information Frankfort, Kentucky

DATE OF PHOTO November 1975

NEGATIVE FILED AT

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Photo of the west facade with its central Palladian feature. (The actual windows at the right of the door replace the original blind windows at a slightly different location.)

PHOTO NO.

3

*25*



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY	
RECEIVED	JAN 16 1976
DATE ENTERED	MAY 28 1976

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

General William O. Butler House

AND/OR COMMON

Same

**2 LOCATION**

CITY, TOWN

Carrollton

\_\_\_ VICINITY OF

COUNTY

Carroll

STATE

Kentucky

**3 PHOTO REFERENCE**

PHOTO CREDIT Public Information Frankfort, Kentucky

DATE OF PHOTO November 1975

NEGATIVE FILED AT

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Photo taken from the northeast showing 20th-century frame addition in the center. The kitchen wing with its mezzanine story is at the left; an original door faces the "patio" from the wing at right. The clapboard wall is modern.

PHOTO NO.

4 of 5





UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY
RECEIVED
JAN 16 1976
MAY 28 1976
DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

General William O. Butler House

AND/OR COMMON

Same

**2 LOCATION**

CITY, TOWN

Carrollton

\_\_\_\_ VICINITY OF

COUNTY

Carroll

STATE

Kentucky

**3 PHOTO REFERENCE**

PHOTO CREDIT Public Information Frankfort, Kentucky

DATE OF PHOTO November 1975

NEGATIVE FILED AT

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Interior photo showing the double panels under the windows and chair-railing in the west parlor.

PHOTO NO.

5 of 5