

(2) View from south

DOE

JN 27 1979

Jul 2 - 1979

Jun Dorgun County



View from southwest showing west wall to be eventaully concealed behind new courthouse annex now under construction

UN 27 1979 JUL 2 - 1979



fan Joaquen County
(3) View from southeast
1 looking at south wall

looking at south wall of theater building

.IUL 2 - 1979



(4) View from southeast showing |San Joaquin | Street frontage



View from northeast showing San Joaquin Street



(6) View from northwest show-ing Fox tower across the courthouse square JUN 27 1979, JUL 2" 10/3



FOX CALIFORNIA THEATER
Stockton, California
Photo by Raymond W. Hillman
January 1979

Negative at Pioneer Museum & Haggin Galleries, Stockton

JUN 27 1979

Looking SW down Main St. from San Joaquin St.

PHOTO #1 7 6

MAY 3 0 1979



FOX CALIFORNIA THEATER
Stockton, California
Photo by Raymond W. Hillman
January 1979

Negative at Pioneer Museum & Haggin Galleries, Stockton

Looking SE across Rotunda immediately inside main entrance

PHOTO #207 6

MAY 3 0 1979 DOE

San Jouquin County

7 1979



DOE

FOX CALIFORNIA THEATER
Stockton, California
Photo by Raymond W. Hillman
January 1979

Negative at Pioneer Museum & Haggin Galleries, Stockton

Looking south through auditorium from balcony

Jan Joaquen County 3 0 1979 PHOTO #3 076



FOX CALIFORNIA THEATER
Stockton, California
Photo by Raymond W. Hillman
January 1979

Negative at Pioneer Museum & Haggin Galleries, Stockton

JUN 27 1979

View along portion of east wall of auditorium showing private box seating section at east end of balcony. Identical box is at west end of balcony.

PHOTO #4 of 6 MAY 3 0 1979

San Jouquin County



DOE JUN 27 1979

FOX CALIFORNIA THEATER
Stockton, California
Photo by Raymond W. Hillman
January 1979

Negative at Pioneer Museum & Haggin Galleries, Stockton

View of portion of east wall of auditorium showing loft for organ pipes covered by oil on canvas landscape.

PHOTO #5 of 6

MAY 3 0 1979

San Jouquin County



DOE JUN 27 1979

FOX CALIFORNIA THEATER
Stockton, California
Photo by Raymond W. Hillman
January 1979

Negative at Pioneer Museum & Haggin Galleries, Stockton

MAY 3 0 1979

Looking up upon typical ceiling detail of auditorium located above balcony along east wall

PHOTO #6 076 San Loaguen County