



Facades of 1715, 1709, 1705 N.W.
Irving Street, facing Northeast.
(Oregon Historical Society,
Negative #R-455)
Portland, Oregon. November, 1973

JAN 4 1980

Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

FEB 12 1980

Oregon Historical Society Photo, 1973
1230 SW Park Avenue
Portland, Oregon 97205

1 of 18

Facades of 1715, 1709, 1705 N.W. Irving,
facing northeast



Front facades of 1715 and 1719
N.W. Irving Street, prior to
restoration, facing North.
(Oregon Historical Society, Negative
#1660) Portland, Oregon. Nov. 1973

JAN 14 1980

Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

Oregon Historical Society Photo, 1973
1230 SW Park Avenue
Portland, Oregon 97205

FEB 12 1980

2 of 18

Front (North) Facades of 1715 and 1719 N.W. Irving Street
prior to restoration



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

FEB 12 1980

3 of 18
Porch and doorway
1715 N.W. Irving Street

JAN 14 1980

Doorway of 1715 N.W. Irving Street
facing North.
Portland, Oregon. August, 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

FEB 12 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

JAN 14 1980

4 of 18

Front elevation, 1709 N.W. Irving,
Front and side elevation, 1705 N.W. Irving

Front facade of 1709 and front and
side facade of 1705 N.W. Irving,
facing Northwest.
Portland, Oregon. August, 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

FEB 12 1980

5 of 18
Roof pediment detail
1709 N.W. Irving

JAN 14 1980

Roof pediment detail, 1709 N.W.
Irving, facing North.
Portland, Oregon. August, 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

6 of 18
Side elevation,
1705 N.W. Irving

FEB 12 1980

JAN 14 1980

Front facade of 1705 N.W. Irving
partial front facade of 719 N.W.
17th Street.
Portland, Oregon. August, 1979



Front facade of 715 and 719 N.W. 17th Street
prior to restoration, facing Northwest.
(Oregon Historical Society, Negative # R-452)
Portland, Oregon. November, 1973

JAN 14 1980

Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

FEB 12 1980

Oregon Historical Society Photo, 1973
1230 SW Park Avenue
Portland, Oregon 97205

7 of 18

Front elevation of 715 and 719
N.W.17th Street, prior to restoration,
from the Northwest



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

8 of 18
Doorway and porch
715 N.W. 17th Street, facing West

FEB 12 1980

Doorway of 715 N.W. 17th Street,
facing West.
Portland, Oregon. August, 1979



SAM
WHOLESALE

Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

FEB 12 1980

9 of 18
Front elevation of 715 and 719
N.W. 17th Street, side elevation
of 1705 N.W. Irving Street

Front facades of 715, 719 N.W. 17th.
partial side facade of 1705 N.W.
Irving Street.
Portland, Oregon. August, 1979



Campbell Townhouses
715-199NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

10 of 18

Interior courtyard windows of
1715 N.W. Irving, facing South

FEB 12 1980

Interior courtyard windows of
1715 N.W. Irving, facing South.
Portland, Oregon. August, 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

11 Of 18
Rear door onto courtyard
715 N.W. 17th Street

FEB 12 1980

Rear door to courtyard, 715 N.W.
17th Street.
Portland, Oregon. August, 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

12 of 18
Fireplace detail
1715 N.W. Irving Street

FEB 12 1980

Fireplace detail, 1715 N.W.
Irving.
Portland, Oregon. August 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

13 of 18

Fireplace
1719 N.W. Irving Street

FEB 12 1980

Fireplace, 1719 N.W. Irving.
Portland, Oregon. August 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

14 of 18
Detail of projecting bay windows,
1715 N.W. Irving Street

FEB 12 1980

Detail of projecting bay
windows, 1715 N.W. Irving.
Portland, Oregon. 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979

1415 SE Sherrett Street
Portland, Oregon 97212

15 of 18

Detail of newel post and stair rail,
1719 N.W. Irving Street

FEB 12 1980

Newel post and stairway, main
entry hall, 1719 N.W. Irving.
Portland, Oregon. August 1979



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon


JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

16 of 18
Detail of wainscotting in
kitchen, 1715 N.W. Irving

FEB 12 1980

Wainscotting detail in kitchen
1715 N.W. Irving.
Portland, Oregon. August 1979



Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

JAN 14 1980

Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County Oregon

17 of 18
Typical condition of interior
prior to restoration

FEB 12 1980

Typical interior of a row-
house, prior to restoration.
Portland, Oregon.
November 1973



Campbell Townhouses
715-19 NW 17th Avenue
1705-19 NW Irving Street
Portland, Multnomah County, Oregon

JAN 14 1980

Catherine Galbraith Photo, 1979
1415 SE Sherrett Street
Portland, Oregon 97212

18 of 18
Detail of interior woodwork,
1715 N.W. Irving Street

FEB 12 1980

Interior woodwork, 1715 N.W.
Irving.
Portland, Oregon. August, 1979