

(Attach 4" x 5" black and white photograph)

REGION RMR PARK/AREA NAME Zion National Park PARK NUMBER 1590

STRUCTURE NAME South Entrance Sign STRUCTURE NUMBER 72

LOCATION OF STRUCTURE South Entrance PARK LOCATION CODE SE

NATIONAL REGISTER _____ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)

NPS LEGAL INTEREST FEE MANAGEMENT AGREEMENT: _____

Check all of the following categories for which NPS has treatment responsibility:

Stabilization() Cyclic Maintenance() Routine Maintenance() Approved Ultimate Treatment()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document _____ () Document Date: / /

Estimated Treatment Costs _____

Stabilization: \$ _____	Date: <u> / /</u>	Level of Estimate: (A) (B) (C)
Approved Treatment: \$ _____	Date: <u> / /</u>	Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: / /1935 Date of Alterations: / /

Architect/Designer: _____ Historical Theme(s): NPS rustic

History of Structure: The South Entrance Sign was constructed by CCC enrollees from Camp NP-2, stationed at Zion, in the Spring of 1935. The stone was quarried from the recently opened Zion Stone Quarry.

Evaluation of Structure: Historic Theme Contributing X Non-Contributing _____

National Register Criteria: A B C XD (Include integrity statement)

Built of local red sandstone and wood rails, the south entrance sign retains its original character and fabric typical of the NPS-Rustic style.

Bibliography: Olivieri, Lance, LCS inventory, 1976; Markoff, Dana, The Dudes are Always Right, 1980, 111.

Representation in Other Surveys: LCS inventory, 1976:

If structure has been removed, how? _____ Date: / /

Report prepared by: Nancy Witherell Date: 10/10/84

LOCATION: Section _____ State _____
 Township _____ County _____
 Range _____

USE: CURRENT INTERIOR USE (NPS 28 CODE) n/a
 Original Use _____
 Intermediate Uses _____

PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

NEGATIVE No. ROLL #18, VIEW 19A

OWNERSHIP: Present Owner: _____ NPS
 Original Owner: _____ NPS
 Intermediate Owner(s): _____ NPS

PHYSICAL DESCRIPTION

TYPE OF STRUCTURE (NPS 28 CODE): MN CHIMNEYS: none

ARCHITECTURAL CHARACTER (STYLE): "NPS-Rustic"

SITE (INCLUDE ORIENTATION OF STRUCTURE): PORCHES: none
 Sign straddles Route 9 at south entrance of Park;

primary face is S; fences run E-W.
 OVERALL BUILDING PLAN (FOOTPRINT):

2 pylons with extended rail fences
 OVERALL DIMENSIONS: E pylon: 11'3" x 13'3"; W pylon: 8'3" x 9'3";

12 stone posts: 1'6" sq.; each fence is 75' in length
 COMPOSITION (NPS 28 CODE): ST WINDOWS: none

STORIES: n/a DOORS: none

FOUNDATION: n/a ADDITIONS: none

WALLS: Pylons are random ashlar, red sandstone, with lower
 courses stepped. Irregular massing on all sides. East pylon
 is primary, with wood hanging Zion sign, and NPS sign. INTERIOR PLAN: n/a

Fences are of stone posts with triple rails.
 ROOF: n/a INTERIOR FINISHES: n/a

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

Stone pylons, wood hanging sign, stone posts with wood rails