



Burlington County, NJ

BARZILLAI NEWBOLD HOUSE

Southwest room, second floor

Fireplace paneling

From southeast

Burlington County Cultural and


Heritage Commission/C.M. Greiff

1976

Photo # 127

AUG 9 1977

JAN 26 1978



BURLINGTON CO, NJ

BARZILLAI NEWBOLD HOUSE

Northwest room, second floor

Wooden latch

Burlington County Cultural and
Heritage Commission/C.M. Greiff
1976

Photo #
287

AUG 9 1977

JAN 26 1978



21073
90879-1-26
C

Burlington County, NJ

BARZILLAI NEWBOLD HOUSE
Interior. east wing. from west
National Trust for Historic
Preservation/T. Slade
1976

Photo

AUG 9 1977

#397

JAN 26 1978



Burlington County, NJ

BARZILLAI NEWBOLD HOUSE
South elevation from south
Burlington County Cultural
and Heritage Commission/
C.M. Greiff

1976

Photo
#487

JAN 26 1978

AUG 9 1977



Burlington Co, NJ

BARZILLAI NEWBOLD HOUSE

View from west

Burlington County Cultural and
Heritage Commission/C.M. Greiff
1976

Photo # 587
AUG 9 1977

JAN 26 1978



Burlington Co, NJ

BARZILLAI NEWBOLD HOUSE

Hall, second floor

"wall safe"

Burlington County Cultural and
Heritage Commission/C.M. Greiff
1976

Photo

AUG 9 1977 # 6 of 7

JAN 26 1978



Burlington Co, NJ

BARZILLAI NEWBOLD HOUSE

Outbuildings

View from northwest

From left: woodshed, corn crib,
log structure

Burlington County Cultural and
Heritage Commission/C.M. Greiff

1976

JAN 26 1978

AUG 9

1977

Photo

737