



The Kentucky Heritage Commission

Name Samuel E. Hill House

Location 519 E. Union Street Hartford, Ohio Co. Kentucky

Photographer Jayne C. Henderson

Date Taken February 1980 MAY 27 1980

Negative Location Kentucky Heritage Commission

View Photo 1 north and east facades Taken from the

north. 1/5 MAR 31 1980



The Kentucky Heritage Commission

Name Samuel E. Hill House

Location 519 E. Union St. Hartford, Ohio Co., Kentucky

Photographer Jayne C. Henderson

Date Taken February 1980 MAY 27 1980

Negative Location Kentucky Heritage Commission

View Photo 2 south facade. Taken from the south.

2/5-

MAR 31 1980



The Kentucky Heritage Commission

Name Samuel E. Hill House

Location 519 E. Union St. Hartford, Ohio Co, Kentucky

Photographer Jayne C. Henderson

Date Taken February 1980

MAY 27 1980

Negative Location Kentucky Heritage Commission

Frankfort, Kentucky

View Photo 3 Interior. Left front parlor mantle.

3/5

MAR 31 1980



The Kentucky Heritage Commission

Name Samuel E. Hill House

Location 519 E. Union St Hartford, Ohio Co. , Kentucky

Photographer Jayne C. Henderson

Date Taken February 1980

MAY 27 1980

Negative Location Kentucky Heritage Commission

Frankfort, Kentucky

View Photo 4 Interior, Left front parlor mantle detail.

4/5

MAR 31 1980



The Kentucky Heritage Commission

Name Samuel E. Hill House

Location 519 E. Union St. Hartford Ohio Co. , Kentucky

Photographer Jayne C. Henderson

Date Taken February 1980

MAY 27 1980

Negative Location Kentucky Heritage Commission

Frankfort, Kentucky

View Photo 5 Interior. Second floor mantle.

57/5

MAR 3 . 1980