Form KHC1985-2 Page 1 of $\frac{3}{2}$ pages

2897 **KENTUCKY HISTORIC RESOURCES**

NOV 1 5 1988

SHELBY SH 228

Form

County

Individual Inv	entory F
1. Name of Resource: CARRISS'S FEED STORE	16. Da
2. Original Owner: J.H. CARRISS	17. Sty
3. Other Names: SOUTHVILLE FEED STORE	13c str
4. Prehistoric Site Building ^X Object Historic Site Structure Other	18 AT
5. Location: MT. EDEN QUAD.; S.W. CORNER KY.55 & 44, SOUTHVILLE	19. No 20. Or SINGL
6. Owner's Name: GERTRUDE SKELTON	21. Sin 22. Ro GABLE
7. Owner's Address: ROUTE 4	23. Str FRAME
SHELBYVILLE, KY. 40065 8. Evaluation:N.R. POTENTIAL [N]	24. Ex
9. Recognition & Date: Nat.Landmark Local Landmark	25. Fo WOOD
Nat.RegisterHABS/HAERHighway MarkerKY Inventory 1986KY Landmark Certificate	26. Ma
10. N.R.Status & Date: 11. N.R.Group:	27. Spe
District Name: [] Mult.Resource Area SHELBY CO MRA [] Thematic Name: []	28. Ou NONE 29. Or
12. Historical Theme:Primary:BUSINESS[05B]SecondaryAGRICULTURE[010]Other:[]]	BUSIN 30. Pro BUSIN 31. Co
13. Statement of Significance:	GOOD 32. En
CARRIS' FEED STORE HAS LOCAL SIGNIFICANCE FOR HISTORIC ASSO- CIATIONS WITH THE AGRICULTURAL AND BUSINESS HISTORY OF RURAL SHELBY COUNTY DURING THE EARLY 20TH CENTURY. [A]	33. At Ro
14. History:	
CARRISS' FEED STORE IS HISTORICALLY AND PHYSICALLY RELATED TO CARRISS' STORE DIRECTLY NORTH AT THE INTERSECTION THAT MAKES SOUTHVILLE. THE 1882 ATLAS OF SHELBY COUNTY INDICATES SCALES AT THIS SITE AT THAT TIME. J.H. CARRISS OPERA- TED A FEEDMILL AND SAWMILL AT THAT TIME HERE AND ACROSS THE ROAD WHERE THE STORE NOW STANDS. SINCE ABOUT 1915, THESE TWO BUILDINGS HAVE HOUSED THE NECESSITIES OF RURAL LIFE, BOTH DOMESTIC AND FARM ASSOCIATED.	

15. Source of historical information and/or contact person:

VIVIAN BOSWELL, ROGER BROWN, DONA SKELTON, 1882 ATLAS OF HENRY AND

16. Date: Original Building	4 [] []
TOC STUMMERCIAL	[^{5x}]
18 Architect/Builder: ATTRIBUTED TO JAMES W. ADAMS	
19. No. of Stories:	[1.0]
20. Original Floor Plan: SINGLE ROOM FEED STORE	[⁰⁰]
21. Single Pile Double Pile N.A	• <u> </u>
22. Roof Form & Material: Original GABLE-ASPHALT SHINGLE Not Original	
23. Structural Material: FRAME	[^W]
24. Exterior Material: CLAPBOARD	<u>רש</u> ו נו
25. Foundation Material: WOOD POST AND PAD	[P]
26. Major Alterations: None X	
Moved/Rebuilt Other	
Additions 27. Special Features:	
28. Outbuildings: NONE	(^{NC})
29. Original Function: BUSINESS	[^{02A}]
30. Present Use: BUSINESS	[02A]
31. Condition:	
GOOD 32. Endangered: Yes	[G]
No	- <u>x</u>
33. Attach Photos:	
Roll ⁴ Photo Nos: ¹⁻ No. of Slide	s:
UT GHE DEU TE D'4 VE LLE D'E	81.94A
HELMER CONTRACTORS IN A CONTRACT NOTES IN THE HELMER CONTRACTORS IN A	an a
n en 1999 de la companya de la comp Esta de la companya d	. ()
1/1 (B) B (111) (ST) (C) (B) (B)	
i se de Élis II seu se se	
and the second of the parts of the second	
	•
	· · · ·

34.	Prepared by:	CHRIST	INE AMOS	
35.	Organization:	SHELBY	CO. HIST.	soc.
36.	Date:	6/1986		
37.	New Survey	<u>X</u>	Resurvey	

Form KHC1985-2

- 0 - 4

	Ā	KENTUCKY HISTORIC RESOURCES Individual Inventory Form			Resource #			
38.	UTM Point of Primary Building: Quadrant: MOUNT EDEN	Zone <u>16</u>	Easting 659260	Northing 4219340	39. 40.	G.I.S. Mod. Coordi.Accuracy]]
11.	UTM Points of Boundary (for N. F A	. eligibl	•					
12.	Total Acreage in Present Propert		43 Acre	age included in	PODOSC	d N.R. boundary:	1	

Site Plan (and boundary description and justification for N.R. sites):

THE BOUNDARIES OF THE PROPERTY FORM A RECTANGLE AROUND THE BUILDING BEGINNIN AT A POINT 15'SE OF THE SE CORNER OF THE BUILDING AT THE WEST EDGE OF KY 53 THEN, WEST 65' TO POINT B; THEN NORTH ON A LINE PARALLEL TO AND 25'WEST OF THE WEST WALL OF THE BUILDING TO THE SOUTH EDGE OF KY 44; THEN EAST ALONG THE SOUTH EDGE OF THE ROAD TO POINT D, THE INTERSECTION OF SAID ROAD AND KY 53; THEN SOUTH ALONG THE WEST EDGE OF KY 53 TO POINT OF ORIGIN.

15. Description and House Plan:

CARRISS'S FEED STORE IS LOCATED IN THE SOUTHWEST CORNER OF THE INTERSECTION OF KY.55 (MT. EDEN RD.) ND KY 44/714 (HEMPRIDGE RD.), DIRECTLY SOUTH OF . . ARRISS'S GROCERY (SH 227). THE FUNCTIONAL BUIL-JING LOOKS MUCH LIKE THE GROCERY: CLAPBOARD SIDING ITH CORNER TRIM; SIX-OVER-SIX SASH WINDOWS, THE IAIN, DOUBLE DOOR ENTRY CENTERED IN THE NORTH FACE ND REACHED BY CONCRETE STEPS; 40' BY 42' OVERALL, INSIDE THE SINGLE ROOM WITH EX-ND A GLBLE ROOF. OSED FRAMING IS A STOVE, WORK BENCHES AND SOME OF HE STOCK NECESSITIES OF LIFE: BAGS OF DOG FOOD, RACTOR HYDRAULIC FLUID, CANING REEDS, BALEING WINE AND NITROGEN.

HE PROPERTY CONTAINS ONE CONTRIBUTING BUILDING.

Continuation Sheet SH 228 Carriss's Grocery

13. Statement of Significance, continued

county paved road system and the widespread acceptance of motorized vehicles made larger towns like Shelbyville daily places to shop. The community of Southville once contained a store, feed store, doctor's office, post office and scales, and the crossroads was a focal point for the surrounding farms. Although times and needs have changed, Southville remains a significant reminder of the patterns of life in rural Shelby County at the turn-of-the-century.