



Battey-Barden House
Plainfield Pike, Scituate, Rhode Island

Providence Ct

Warren Jagger, photographer
Negative: Rhode Island Historical Preservation Commission

October, 1979

JUL 23 1980

View of house from north northeast.

Photo #1/5

AUG 29 1980



Battey-Barden House
Plainfield Pike, Scituate, Rhode Island

Providence Co.

JUL 23 1980

Warren Jagger, photographer October, 1979
Negative: Rhode Island Historical Preservation Commission

Front stair hall looking east, showing staircase and
remaining original stencil patterns.

Photo #2/5

AUG 29 1980



Batthey-Barden House
Plainfield Pike, Scituate, Rhode Island

Providence Co.

Warren Jagger, photographer

October, 1979

Negative: Rhode Island Historical Preservation Commission

JUL 23 1980

Northeast parlor: view west; note chair rail, reeding of
mantel pilasters, and fact that reproduced stencil
pattern is omitted above mantel and below chair rails.

Photo #3/5

AUG 29 1980



Battey-Barden House
Plainfield Pike, Scituate, Rhode Island

JUL 23 1980
*Providence
Co.*

Warren Jagger, photographer
Negative: Rhode Island Historical Preservation Commission

October, 1979

Northeast parlor: view northeast, showing fields of
stencil patterns; original patterns repainted.

Photo #4/5

AUG 29 1980



Battey-Barden House
Plainfield Pike, Scituate, Rhode Island

Providence Co

Warren Jagger, photographer

October, 1979

Negative: Rhode Island Historical Preservation Commission

JUL 23 1980

Kitchen: view east, through to present bathroom.
Stencil pattern adapted from Willard House, Still River,
Massachusetts. Note typical fireplace with cut granite
hearth.

AUG 29 1980

Photo # *5/5*