United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form



See instructions in *How to Complete National Register Forms* Type all entries—complete applicable sections

1. Name	
historic Peter Paul Shule	Barn
and/or common Shule Barn	
2. Location	
street & number Denny Road	N∕A_ not for publication
city, town Sylvia mc.	_X_vicinity of Sylvi&ongressional district Sixth
state Tennessee co	ode 047 county Dickson code 043
3. Classification	
Category district public building(s) private structure both object in process N/A being considered	Status Present Use X occupied X agriculture museum unoccupied commercial park work in progress educational private residence Accessible entertainment religious X yes: restricted government scientific yes: unrestricted industrial transportation no military other:
name Howard Garvey street & number Route 4, Box 1	44
city, town Dickson	X vicinity of Sylvia state Tennessee 37055
5. Location of Leg	gal Description
courthouse, registry of deeds, etc.	Registrar's Office
street & number	Dickson County Courthouse
city, town	Charlotte state Tennessee 37036
6. Representation	n in Existing Surveys
title None	has this property been determined elegible? yes _X_ no
_{date} N/A	N/A federal state county local
depository for survey records N/A	
city, town N/A	state N/A

Condition		Check one	Check one	
excellent	deteriorated	unaltered	_X_ original site	
X good	ruins	_X_ altered	moved date	
fair	unexposed			

Describe the present and original (if known) physical appearance

7. Description

Located in rural Dickson County near the Sylvia community, the Shule Barn is an excellent example of one method of 19th century barn construction. The plain exterior appearance is not indicative of the sophisticated structural system which uses the heavy timber frame construction method employing hand hewn oak timbers connected with pegged mortise and tenon joints.

The basic plan is rectangular (66'x40') but has an uncommon division of interior space. Most barns in Tennessee of this size are similar to the "English" barn style (Arthur and Witney 1972: 69) which has three bays and central wagon doors with a transverse runway or alley. The Shule barn has a five bay interior due to four interior bents, two transverse runways, and two pairs of exterior doors (see plan, Fig. 1).

The bents are constructed of hand hewn (9"x9"+) posts mortised into hewn log sills which rest on flat fieldstone pier foundations. Interior posts are supported by fieldstone piers and replacement concrete pads. The basic bent configuration (Fig. 2) consists of five vertical posts; the two outside or wall posts are connected with a single 40 foot long hewn tie beam mortised into the wall posts. The tie beam is supported by three interior vertical posts mortised into the tie beam. Another run of hewn beams, parallel to the tie beam, are mortised into the five vertical posts. The mortise and tenon joints are pegged with square trenails in 1" diameter holes. Diagonal bracing at the wall posts and center post is accomplished using 3"x5" braces which have been cut with a radial saw. These are the only sawmill produced parts of the bent structure. The angled braces are mortised into the post and beams but are not pinned.

The gable end bents are symmetrical, having a central post, but the interior bents at transverse section A-A' and B-B' are asymmetrical to the extent that the central post is 2 1/2 feet east of the center line (Fig. 1 and 2). There is no physical evidence that the center posts have been relocated and it is unlikely that the barn has been widened since the tie beams are single unspliced logs.

The roof framing system consists of hewn purlins braced with angled purlin posts (hewn) mortised into the tie beam. Each of the purlin posts is braced with a diagonal hewn timber which is also mortised into the top of the tie beam (Fig. 2). The rafters are sawn (radial sawmarks) and are supported by the hewn wall plates and purlins. The rafters are tied together at the ridge line with half-lapped and pegged joints. The roof is a simple gable shape and is presently covered with 5-"V" type galvanized sheet metal and modern sheathing.

The present siding is unpainted vertical boards nailed to the timber frame with machine-made, machine-headed cut nails. This may not be the original siding but is probably attached in the same manner as the original. Cut nails of this type were in popular use from ca. 1840 to ca. 1890.

UNITED STATES DEPARTMENT OF THE INTERIOR HERITAGE CONSERVATION AND RECREATION SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR HCRS USE ONLY
RECEIVED DEC 1 2 1980
DATE ENTERED

Peter Paul CONTINUATION SHEET Shule Barn

ITEM NUMBER 7

PAGE 2

Alterations to the barn are limited to a shed addition on the east side, new rafters, sheathing and roof material, a hay hoist tract, hay hoist dormer on the north gable end, and interior partitions. The original wagon doors have been replaced with hanging sliding doors with commercial track hardware. One piece of hand forged door hardware is still extant. One traditional style interior door remains (Photo 6 of 6).

The barn is currently used to house sheep and is part of an operating farm.

8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799X 1800–1899 1900–	Areas of Significance—C archeology-prehistoric archeology-historicX_ agricultureX_ architecture art commerce communications	•	ng landscape architectur law literature military music	e religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1871-72	Builder/Architect Pe	eter Paul Shule, farmer	•

Statement of Significance (in one paragraph) Criterion C

The Shule Barn has integrity of location, design, setting, materials and workmanship, and embodies the distinctive characteristics of the heavy timber frame method of construction used in the 19th century in rural Tennessee. The internal plan is of an uncommon arrangement which has five bays, two transverse runways or alleys, rather than the more common three bay, central runway plan. The bent configuration also is atypical since the interior bents are not symmetrical like the gable end bents.

Although the statewide distribution of barn construction types is not fully known, the date of construction, the type of construction, and unusal plan make this barn a significant example of rural vernacular architecture. It represents the degree of architectural sophistication that went into the design and construction of important farm buildings by non-academically trained builders. According to Shule family records the barn was constructed in 1871-72 by Peter Paul Shule (the name has since been anglicized to Sheley), who came to Dickson County in 1869 from Pennsylvania.

9. N	Majo i	r Bib	liogra	aphic	al Re	efere	nces			
				W	IM KO	j midi	FIED	·		
			, Dudley ety, Ltd		arn, A V		g Landma	ark in N	lorth Ameri	ca.
	•		•				ar intende	HENCIN		
10.	Geo	<u>grap</u>	nical	Data		LÄÜL M				•
	gle name.		ny <u>la</u> r, Tenne					Quadrang	gle scale <u> </u>	:24000
A 1 6 Zone C G G	Easting		4 0 0 4 4 4 4 4 4 4 4 4 4 4 4 4			Zone D	Easting		Northing	1 1
e north close a chitec	n and we a rectan <u>turally</u>	est, by ngular a <u>signifi</u>	arbitrar rea roug <u>cant bui</u>	y lines hly 200	100 feet feet by n the wo	t south 200 fee orking f	and eas t or 1 a arm. T	t of the acre. T he house	efined by E barn, whi here are r is conten	ch toget o other
state		N/A		code	cou	nty	N/A	·	code	
state	1	N/A		code	cou		N/A		code	
11.	Forn	n Pre	pare	d By						
name/titie		Georg	e F. Fie	lder, Hi	storical	Archae	ologist		•	
organizat	ion Ten	nessee	Historic	al Commi	ssion		date	Septemb	er 5, 1980	
street & n	umber	4721	Trousda	le Drive		1	telephone	615/7	41-2371	
city or to	wn	Nach	ville			,	state To	ennessee	37219	
				Pres	serva	tion			ertific	ation
	• • • • • • • • • • • • • • • • • • • •	***************************************		ty within th	<u> </u>					
		national		state	_X_loca	al .				
665), I hei	eby nomir	nate this p	roperty for		the Nation	nal Registe	r and certi	fy that it h	et of 1966 (Pub as been evalu in Service.	
State Hist	oric Prese	rvation Of	ficer signa	ture	refert	L. Ho	yer_		Verleit	12.10
title E)	kecutive	Direct	or, Tenn	essee Hi	storical	Commis	<i>()</i> sion	date	12/1/80	4/1
	RS use only reby certif		property is	s included in	Ent	nal Registe ered in	regarded was assert to the party of the part	date	رار د	m
Kéeper Attest:	of the Nati	onal Regi	ster					 ∳date		

FHR-8-300A (11/78)

UNITED STATES DEPARTMENT OF THE INTERIOR HERITAGE CONSERVATION AND RECREATION SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM


FOR HCRS USE ONLY
RECEIVED DEC 1 2 1980
DATE ENTERED.

Peter Paul CONTINUATION SHEET Shule Barn

ITEM NUMBER 10

PAGE 2

the barn but has been so altered in terms of materials and style as to preclude it from inclusion.



SHULE BARN

Vicinity of Sylvia, Dickson County, Tennessee

Boundaries outlined in red




Figure 2. Transverse Section A-A'; bent framing showing asymmetrical center post arrangement. Traced from measured sketch drawn in field by SHPO staff.

