



1. Holden - Harolt site
2. Aspen, Colorado
3. Roxanne Eflin
4. Summer, 1989
5. Aspen City Hall
6. Sampling works Bldg - looking SE
7. # 1



1. Holden - Marolt site
2. Aspen, Colorado
3. Roxanne Eflin
4. Summer, 1989
5. Aspen City Hall
6. Sampling work along # Salt shed
looking SE
7. # 2



1. Holden-Marolt Site
2. Aspen, Colorado
3. Roxanne Etlm
4. Summer, 1989
5. Aspen City Hall
6. (Complex-entirely) looking SW
7. #³



1. Holden-Marolt Site

2. Aspen, Colorado

3. Roxanne Eflin

4. Summer, 1989

5. ASPEN City Hall

6. Sampling Worker Bldg - looking N

7. # 4



1. Haldon-Marolt site
2. Aspen, Colorado
3. Roxanne Eflin
4. Summer, 1989
5. Aspen City Hall
6. Salt shed - left
opal Marolt house - center
Sampling works' Bldg. - right
7. # 5



1. Holden Mining and Smelting Company
2. Aspen, Colorado
3. Roxanne Eflin, photographer
4. July, 1989
5. Aspen City Hall - neg 5
6. view of non-contributing Opal Marolt house (original Holden office) looking east
7. # 6



1. Holden Mining and Smelting Company
2. Aspen, Colorado
3. Roxanne Eflin, Photographer
4. July, 1989
5. Aspen City Hall - negs.
6. View of mill ruins looking west
7. # 7



1. Holden-Marolt site
2. Aspen, Colorado
3. Roxanne Eflin
4. Summer, 1989
5. Aspen City Hall
6. Mill ruins - looking SW
7. # 7



1. Holden Mining & Smelting Co.
2. Aspen, Colo.
3. Rick Newton
4. Sept. 1989
5. Aspen, CO
6. Views of foundation & structural system
(sampling works)



1. Holden Mining & Smelting Co.
2. Aspen, CO
3. Rick Newton
4. Sept. 1989
5. Aspen, CO
6. Views of foundation & structural
(sampling works) system



1. Holden Mining & Smelting Co.

2. Aspen, CO

3. Rick Newton

4. Sept. 1989


5. Aspen City Hall

6. View of foundation & structural
system (sampling works)

#9



1. Holden Mining & Smelting Co
 2. Aspen, CO
 3. Rick Newton
 4. Sept. 1989
 5. Aspen City Hall
 6. Interior stair leading to 2nd floor
(not original)
- Sampling works



1. Holden Mining & Smelting Co.
2. Aspen, CO
3. Rick Weston
4. Sept. 1989
5. Aspen City Hall
6. Interior view of 2nd floor
structural beams - Sampling
works



1. Holden Mining & Smelting Co.
2. Aspen, CO
3. Rick Weir
4. Sept. 1989
5. Aspen City Hall
6. Interior view of structural cross
bracing - Sampling works



STORE
ON END
ONLY

1. Hilder Mining & Smelting Co.
2. Aspen, CO
3. Rick Newton
4. Sept. 1989
5. Aspen City Hall
6. Interior views of 2nd floor
structural cross bracing
sampling work

11/5



1. Holden Mining & Smelting Co
2. Aspen, Colorado
3. Rick Newton
4. Sept. 1999
5. Aspen, Colorado
6. View of foundation and structural system (Sampling works)