



Aals
MANUFACTURING COMPANY

Aalfs Building Front
View from southwest

Boston Block
1005-13 East Fourth
Sioux City, Woodbury County, Iowa
Photo No. 1
By: William E. Rodawig
Date: September 1984
View: west and south facades from SW



Aalfs Building Front
View from southeast

Boston Block
1005-13 East Fourth Street
Sioux City, Woodbury County, Iowa
Photo No. 2
By: William E. Rodawig
Date: September 1984
View: south and east faces from SE



Aalfs Building Rear
View from northeast.

Boston Block
1005-13 East Fourth St.
Sioux City, Woodbury County, Iowa
Photo No. 3
By: William E. Rodawig
Date: September 1984
View: east and north facades from NE



Aalfs Building Rear
View from northwest

Boston Block
1005-13 East Fourth St.
Sioux City, Woodbury County, Iowa
Photo No. 4
By: William E. Roadwig
Date: September 1984
View: north and west facades, from NW



Aalfs Building
Detail cast iron work at
front entry

Boston Block

1005-13 East Fourth St.

Sioux City, Woodbury County, Iowa

Photo No. 5

By: William E. Rodawig

Date: September 1984

View: cast iron detail, main facade.



Aalfs Building
Detail metal window frame
upper floors

Boston Block

1005-13 East Fourth St.

Sioux City, Woodbury County, Iowa

Photo No. 6

By: William E. Rodawig

Date: September 1984

View: Detail, main facade window



Aalfs Building
Detail of bolted cast iron
superstructure

Boston Block
1005-13 East Fourth Street
Sioux City, Woodbury County, Iowa
Photo No. 7
By: William E. Rodawig
Date: September 1984
View: Interior detail, cast iron
column, note roller marks used
to guide assembly.



Aalfs Building
Atrium with parquet floor
First floor entry

Boston Block
1005-13 East Fourth St.
Sioux City, Woodbury County, Iowa
Photo No. 8
By: William E. Rodawig
Date: September 1984
View: Interior, atrium floor (shows
herringbone pattern created by
slicing up removed joists)



Aalfs Building
Elevator shaft and stairway
First floor

Boston Block
1005-13 East Fourth St.
Sioux City, Woodbury County, Iowa
Photo No. 9
By: William E. Rodawig
Date: September 1984
View: Interior, first floor stairway
and elevator shaft.



Aalfs Building
Elevator car and shaft
Second floor

Boston Block

1005-13 East Fourth St.

Sioux City, Woodbury County, Iowa

Photo No. 10

By: William E. Rodawig

Date: September 1984

View: interior, second floor elevator



Boston Block
1005-13 East Fourth St.
Sioux City, Woodbury County, Iowa
Photo No. 11
By: William E. Rodawig
Date: September 1984
View: interior, detail of newel post

Aalfs Building
Detail stairposts with
new ball