



EXCHANGE BANK BUILDING 201 South Monroe St., Tallahassee (Leon County), Florida Susan Hamburger 1983 Susan Hamburger West (entrance) and north facades Photo no. 1 of 9



EXCHANGE BANK BUILDING 201 South Monroe St., Tallahassee (Leon County), Florida Susan Hamburger 1983 Susan Hamburger East (rear) and south facades Photo no. 2 of 9



EXCHANGE BANK BUTTDING 201 South Monroe St., Tallahassee (Leon County), Florida Photographer unknown 1928 Copied from 7th/8th Annual Report, City of Tallahassee Photo no. 3 of 9 West (entrance) and north facades




EXCHANGE BANK BUILDING 201 South Monroe St., Tallahassee (Leon County), Florida Susan Hamburger 1983 Susan Hamburger Cast stone detail over main entrance Photo no. 4 of 9



EXCHANGE BANK BUTLDING 201 South Monroe St., Tallahassee (Leon County), Florida Susan Hamburger 1983 Susan Hamburger Cast stone detail over main entrance Photo no. 5 of 9



EXCHANGE BANK BUILDING 201 South Monroe St., Tallahassee (Leon County), Florida Susan Hamburger 1983 Susan Hamburger Cast stone detail between 2nd & 3rd floor Photo no. 6 of 9



EXCHANGE BANK BUILDING 201 South Monroe St., Tallahassee (Leon County). Florida Susan Hamburger 1983 Susan Hamburger Terra cotta detail on cornice Photo no. 7 of 9



EXCHANGE BANK BUTLDING 201 South Monroe St., Tallahassee (Leon County), Florida Susan Hamburger 1983 Susan Hamburger Mail tube drop, interior lobby Photo no. 8 of 9



EXCHANGE BANK BUILDING 201 South Monroe St., Tallahassee (Leon County), Florida Susan Hamburger 1983 Susan Hamburger First floor hallway Photo no. 9 of 9