



NAME: Blacksmith Shop (#82), Rocky Mountain  
National Park Utility Area Historic District  
LOCATION: Rocky Mountain National Park  
PHOTOGRAPHER: Rodd L. Wheaton  
DATE: March, 1976  
LOCATION OF NEGATIVE: Rocky Mountain Regional  
Office, Denver, CO  
VIEW: Looking west  
PHOTO NUMBER: 1

FEB 16 1982



NAME: Annex-Mess Hall (#24), Rocky Mountain  
National Park Utility Area Historic  
District

LOCATION: Rocky Mountain National Park

PHOTOGRAPHER: Rodd Wheaton

DATE: March, 1976

LOCATION OF NEGATIVES: Rocky Mountain  
Regional Office, Denver, CO

VIEW: East elevation taken from north-east

PHOTO NUMBER: 2

FEB 16 1982



NAME: Equipment Building(#75), Rocky  
Mountain National Park Utility Area  
Historic District

LOCATION: Rocky Mountain National Park

PHOTOGRAPHER: Rodd L. Wheaton

DATE: March, 1976

LOCATION OF NEGATIVE: Rocky Mountain  
Regional Office, Denver, CO

VIEW: North elevation, look from south

PHOTO NUMBER: 3

FEB 16 1982



NAME: Fire Tool Cache Building (#87),  
Rocky Mountain National Park Utility  
Area Historic District

LOCATION: Rocky Mountain National Park

PHOTOGRAPHER: Rodd L. Wheaton

DATE: March, 1976

LOCATION OF NEGATIVE: Rocky Mountain  
Regional Office, Denver, CO

VIEW: West elevation looking east

PHOTO NUMBER: 4

FEB 16 1982





NAME: Maintenance Buildings Rocky Mountain  
National Park Utility Area Historic District  
LOCATION: Rocky Mountain National Park  
PHOTOGRAPHER: Rodd Wheaton  
DATE: March, 1976  
LOCATION OF NEGATIVE: Rocky Mountain Regional  
Office, Denver, CO  
VIEW: South  
PHOTO NUMBER: 5

FEB 16 1982



NAME: Residence (#5), Area B Rocky Mountain  
National Park Utility Area Historic District  
LOCATION: Rocky Mountain National Park  
PHOTOGRAPHER: Jim Muhn  
DATE: July, 1976  
LOCATION OF NEGATIVE: Rocky Mountain  
Regional Office, Denver, CO  
VIEW: Facing north  
PHOTO NUMBER: 6

FEB 16 1982



NAME: Residence (#47), Rocky Mountain National  
Park Utility Area Historic District  
LOCATION: Rocky Mountain National Park  
PHOTOGRAPHER: Jim Muhn  
DATE: July, 1976  
LOCATION OF NEGATIVE: Rocky Mountain  
Regional Office, Denver, CO  
VIEW: Looking south west  
PHOTO NUMBER: 7

FEB 16 1982





NAME: Residence (#46), Rocky Mountain  
National Park Utility Area Historic District  
LOCATION: Rocky Mountain National Park  
PHOTOGRAPHER: Jim Muhn  
DATE: July, 1976  
LOCATION OF NEGATIVE: Rocky Mountain Regional  
Office, Denver, CO  
VIEW: Looking west  
PHOTO NUMBER: 8

FEB 16 1982





---

NAME: Beaver Meadows Visitor Center, Rocky  
Mountain National Park Utility Area  
Historic District

LOCATION: Rocky Mountain National Park

PHOTOGRAPHER: Richard A. Borjes

DATE: September. 1981

LOCATION OF NEGATIVE: Rocky Mountain Regional  
Office, Denver, CO

VIEW: Looking south-eastward--front elevation of  
building.

PHOTO NUMBER. 9

FEB 16 1982

---



RESTROOMS

Restrooms are located inside the building near the entrance. They are open to the public and are free of charge. They are located on the first floor of the building.

1988

10.25.11.10

NAME: Beaver Meadows Visitor Center, Rocky  
Mountain National Park Utility Area  
Historic District

LOCATION: Rocky Mountain National Park

PHOTOGRAPHER: Richard A. Borjes

DATE: September, 1981

LOCATION OF NEGATIVE: Rocky Mountain Regional  
Office, Denver, CO

VIEW: Front entrance

PHOTO NUMBER: 10

FEB 16 1982



NAME: Beaver Meadows Visitor Center, Rocky  
Mountain National Park Utility Area  
Historic District

LOCATION: Rocky Mountain National Park

PHOTOGRAPHER: Richard A. Borjes

DATE: September 1981

LOCATION OF NEGATIVE: Rocky Mountain Regional  
Office, Denver, CO

VIEW: Detailed view of front

PHOTO NUMBER: 11

FEB 16 1982



NAME: Beaver Meadows Visitor Center, Rocky  
Mountain National Park Utility Area  
Historic District

LOCATION: Rocky Mountain National Park

PHOTOGRAPHER: Richard A. Borjes

DATE: September, 1981

LOCATION OF NEGATIVE: Rocky Mountain  
Regional Office, Denver, CO

VIEW: Detail at front entrance

PHOTO NUMBER: 12

FEB 16 1982