



JACK CREEK GUARD STATION (48CR4074)  
Cabin front (east end) exterior, pole  
fences, picnic table, environment

Photo taken facing west

July 1985

Negative at Medicine Bow Nat'l Forest



JACK CREEK GUARD STATION (48CR4074)  
Cabin south side exterior, picnic  
table, environment

Photo taken facing north  
October 1984

Slide at Medicine Bow National Forest



JACK CREEK GUARD STATION (48CR4074)

Cabin construction detail: sawn log  
dovetail notching, hewn corners

Photo taken facing southwest

July 1985

Negative at Medicine Bow NF



JACK CREEK GUARD STATION (48CR4074)

Cabin interior furnishings: wood/gas  
stove, bunk beds, cabinets, etc.

Photo taken facing west

July 1985

Negative at Medicine Bow NF





JACK CREEK GUARD STATION (48CR4074)

Cabin interior detailing: split pole  
wedge chinking, brick chimney, etc.

Photo taken facing west

July 1985

Negative at Medicine Bow NF