		Utah State Historical Society				au u BV 04 C 18 2 5			
Property Type:			Historic	Preservation Re	Site No. <u>BV-04-C-18-3-5</u> SIGN, SITE # 114				
			Struct	ure/Site Infor	mation Form				
IDENTIFICATION	Street Address: 290 No. 600 East						UTM: 12 357500 4237650		
	Name of Structure):				Т.	R.	S.	
	Present Owner: Keith & Evelyn Warby						Less than one Acre		
	Owner Address:	Beaver,	r, Utah 84713						
	Year Built(Tax Re Legal Description	·	902	Effective Age: Kind of Building:	1908 residence	Tax #:	B384		
	Lot 3, Blk 18, Beaver City Sur.								

2	Original Owne	er: Carol	ine Fotheringham,	Construction Date: 1901		Demolition Date:			
s/USE	Original Use: residence			Pres o nt Us	e: residenc	e			
STATUS/USE	Building Condition:		Integrity:	Preliminary Evaluation:		Final Register Status:			
	🖄 Excellent	Site	Unaltered	□ ^X Significant	Not of the	National Landmark	District		
	🗋 Good	Ruins	X Minor Alterations	Contributory	Historic Period	National Register	Multi-Resource		
	Deteriorated		Major Alterations	Not Contributory		State Register	Thematic		
3	Photography:	Photography: Date of Slides:		Slide No.:	Date of Phot	Photographs: Photo No.:			
	Views: 🗆 Front 🗇 Side 🗆 Rear 🔲 Other			Views: 🗆 Front 🗆 Side 🗆 Rear 🖾 Other					
CUMENTATION	Research Sources:								
ITA	X Abstract of Title	e 🗆 Sar	nborn Maps	Newspapers		🗆 U of U Library			
Ш.	Plat Records / M	ap 🛛 🗆 Cit	y Directories	Utah State Historical Society		BYU Library			
NO.	🕅 Tax Card & Phot	to 🗆 Bio	graphical Encyclopedias	X Personal Interviews		USU Library			
od	Building Permit	🗆 Ob	iturary Index	LDS Church Archives		SLC Library			
<u>ц</u>	Sewer Permit	🗆 Co	unty & City Histories	LDS Genealogical Society		f x Other field work			

~

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

1933 photo on tax card County Assessor's Office

Mrs. Keith Warby interviewed 8/11/80 in Beaver by L.L. Bonar

Street Address:		Site No:
Architect/Builder:	unknown	
Building Materials:	brick, frame & stucco	
Building Type/Style:	second empire, venacular	

Description of physical appearance & significant architectural features:

(Include additions, alterations, ancillary structures, and landscaping if applicable) This one and one-half story house is built in a vernacular version of the Second Empire style. It has a double-pitched "Mansard" roof, verticle lines and dormer windows that penetrate the cornice line. It is built of local brick and the entire home rests upon a black, rubble rock foundation. The brickwork displays a common bond and the mortar joints are white. There is a broad, plain cornice that encircles the home along the eave-line, broken only by the dormer windows. Originally, there was one central chimney in this hall and parlor house, but flues have since been both added and torn down.

The front facade faces south and inward on the lot. The piercing pattern on front is unusual, consisting of two doors on the ground floor with two dormer windows directly above them. Sometime before 1950 a window was added to the front on the ground floor. There was a porch at one time too, and though it is no longer extant, the old rafters would indicate that it did not fully cover either of the two front doors.

While the front facade is not very regular in appearance, the other three facades display rigid bilateral symmetry. There are two dormer windows directly above two regular windows on the north facade and one-above-one on both the west and east ends.

Statement of Historical Significance:

Construction Date:

The Caroline Fotheringham House is significant because of its native brick building materials, its remaining architectural integrity and its vernacular, Second Empire style.

While its builder is unknown, it is likely that it was a non-professional person because of the unusual piercing pattern on the front facade.