



BICYCLE RACES
7 PM JUNE 23
SEATING AVAILABLE
QUARRIER & HALE ST

CAPITOL PLAZA

Union Mission

CROS

CAPITOL THEATER, Charleston, WV.

Photographed by Ms. Morgan Peyton, June,
1985. Photo negative located at 123 Summers
Street, Charleston, WV.

Front facade of building.

Photograph 1.



CAPITOL THEATER, Charleston, WV.

Photographed by Ms. Morgan Peyton, June,
1985. Photo negative located at 123 Summers
Street, Charleston, WV.

Window treatment showing brick/stucco
deterioration; upper front facade.

Photograph 2.



BICYCLE RACES
7 PM JUNE 23
SEATING AVAILABLE
QUARRIER & HALE ST

CAPITOL PLAZA

CAPITOL THEATER, Charleston, WV.


Photographed by Ms. Morgan Peyton, June,
1985. Photo negative located at 123 Summers
Street, Charleston, WV.

Upper storefront facade of building.

Photograph 3.



Photograph of the Plaza Theatre in its original architectural appearance as described in the Consolidated Amusement Co. lease. Photo courtesy of Charleston Newspapers.



PLAZA THEATRE, Charleston, WV

Photograph courtesy of Charleston Newspapers.
Photo negative location unknown.

East facade of The Plaza Theatre (c. 1924)
in its original architectural appearance.

Photograph 4.

BICYCLE RACES
1 7 PM JUNE 23
SEATING AVAILABLE
QUARRIER & HALE ST

CAPITOL PLAZA

Union Mission




CAPITOL THEATER, Charleston, WV

Photographed by Ms. Morgan Peyton, June
1985. Photo negative located at 123
Summers Street, Charleston, WV.

Theater marquee and Deco storefront
treatment, eastern front facade of building.

Photograph 5.





CAPITOL THEATER, Charleston, WV.

Photographed by Paul D. Marshall, December,
1984. Photo negative located at 1033
Quarrier Street, Suite 406, Charleston, WV.

Interior view: Art Deco lobby (c. 1956).
View looking west into the auditorium.

Photograph 6.




CAPITOL THEATER, Charleston, WV.


Photographed by Ms. Morgan Peyton, June,
1985. Photo negative located at 123
Summers Street, Charleston, WV.

Theater interior; First floor auditorium,
facing west, under rehabilitation.

Photograph 7.



Patterned Plaster Ceiling




CAPITOL THEATER, Charleston, WV.


Photographed by Ms. Morgan Peyton, June,
1985. Photo negative located at 123
Summers Street, Charleston, WV.

Theater interior: Decorative plaster ceiling
with classical acanthus motif ending in
rosettes.

Photograph 8.



View of Stage From Balcony



CAPITOL THEATER, Charleston, WV.

Photographed by Ms. Morgan Peyton, June, 1985. Photo negative located at 123 Summers Street, Charleston, WV.

Theater interior: Proscenium view and ceiling grating. View from upper balcony.

Photograph 9.



CAPITOL THEATER, Charleston, WV.

Photograph by Ms. Morgan Peyton, June,
1985. Photo negative located at 123
Summers Street, Charleston, WV.

Theater interior: Fragments of relief
frieze band being restored around
proscenium/stage area.

Photograph 10.



CAPITOL THEATER, Charleston, WV

Photographed by Ms. Morgan Peyton, June,
1985. Photo negative located at 123
Summers Street, Charleston, WV.

Theater interior: Articulated balustrade
looking upward from first floor into second
floor mezzanine.

Photograph 11.



CAPITOL THEATER, Charleston, WV.

Photographed by Ms. Morgan Peyton, June,
1985. Photo negative located at 123
Summers Street, Charleston, WV.

Theater interior: Decorative plaster
medallion for light fixtures, mounted on
ceiling below balcony.

Photograph 12.