



1. James W. Wallace House (HS-461)
8230 Brandywine Road
Northfield, Ohio
2. Photographed by Chester Hamilton in September,
1982.
3. Negative maintained by the Technical Assistance
and Professional Services Division of the
Cuyahoga Valley National Recreation Area.
4. Film number 16653 frame number 1 showing the
northeast corner and north side of the James W.
Wallace House. Photo No. 1



Wallace Farm

8230 Brandywine Rd., Northfield Center vic.

Summit County, Ohio

October 1984

Photographer: Steven Elkinton

Negs: OHPO

view: concrete block building



1. C1900 view of Brandywine Mills with Wallace Farm in background.
8230 Brandywine Road
Northfield, Ohio
2. Photographed C1900 by unknown photographer
3. Negative maintained by the Technical Assistance and Professional Services Division of the Cuyahoga Valley National Recreation Area.
4. Photo No. 3 showing the 19th Century bridge and Brandywine Mills in foreground and the James W. Wallace house and the destroyed barn in background.



Brandywine Falls in 1887. Photo taken by Mr. Hilliard of Washington Street, Bedford,,Ohio. Original photo furnished by Bedford Historical Society.

4 X 5 negative maintained by CUVA

1. Brandywine Mills/Wallace Farm NRHP nomination.
2. The mill and farm are located approximately 2 miles south of Northfield, Ohio.
3. Photograph taken in 1887 by Mr. Hilliard of Washington Street in Bedford, Ohio.
4. Original photograph maintained by the Bedford Historical Society, Bedford, Ohio.
5. Photo taken from just below Brandywine Creek Falls, showing the Brandywine Grist Mill along the south side of Brandywine Creek & the mill dam across the creek.
6. Photograph number 4.



Wallace Farm

8230 Brandywine Rd., Northfield Center vic.

Summit County, Ohio

October 1984

Photographer: Steven Elkinton

Negs: OHPO

view: frame barn