



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED FEB 8 1977

APR 29 1977

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Merit-Tandy Farmstead

AND/OR COMMON

Tandy-Tillotson House

2 LOCATION

CITY, TOWN Patriot

VICINITY OF

COUNTY
Switzerland

STATE
Indiana

3 PHOTO REFERENCE

PHOTO CREDIT Ann Farnsley

DATE OF PHOTO

NEGATIVE FILED AT 301 West Market St., Vevay, Ind.

1976

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

East elevation of the Merit-Tandy House

1



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY
RECEIVED FEB 8 1977
DATE ENTERED APR 29 1977

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Merit-Tandy Farmstead

AND/OR COMMON

Tandy-Tillotson House

2 LOCATION

CITY, TOWN

Patriot

VICINITY OF

COUNTY

Switzerland

STATE

Indiana

3 PHOTO REFERENCE

PHOTO CREDIT Ann Farnsley

DATE OF PHOTO

NEGATIVE FILED AT 301 W. Market St., Vevay, Indiana

1976

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

South elevation of the Merit-Tandy House, showing the additions
to the northwest corner and the southwest area.

PHOTO NO.

2



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY	
RECEIVED	FEB 8 1977
DATE ENTERED	APR 29 1977

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Merit-Tandy Farmstead

AND/OR COMMON

Tandy-Tillotson House

2 LOCATION

CITY, TOWN

Patriot

X VICINITY OF

COUNTY

Switzerland

STATE

Indiana

3 PHOTO REFERENCE

PHOTO CREDIT

Ann Farnsley

DATE OF PHOTO

NEGATIVE FILED AT 301 W. Market St., Vevay, Indiana

1976

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

Round brick ice house found in back of Merit-Tandy House
looking northwest

3



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY	
RECEIVED	FEB 8 1977
DATE ENTERED	APR 29 1977

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Merit-Tandy Farmstead

AND/OR COMMON
Tandy-Tillotson House

2 LOCATION

CITY, TOWN
Patriot

VICINITY OF

COUNTY
Switzerland

STATE
Indiana

3 PHOTO REFERENCE

PHOTO CREDIT Ann Farnsley

DATE OF PHOTO

NEGATIVE FILED AT 301 W. Market St., Vevay, Indiana

1976

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

South and east elevations of the old barn showing the wooden silo

4