	ORIC RESOURCES INVENTORY	DEC BIS SEC		005	FOR OFFICE USE ONLY			
			30%		Town No.: Site No.:		No.:	
HIST-6 REV. 6/83 STATE OF CONNECTICUT CONNECTICUT HISTORICAL COM			MISSION		UTM 1 18 61	7:716:50	4605660	
	59 SOUTH PROSPECT STREET, HARTF		CUT 0610	6	QUAD:		4,00,00,000	
1	~ (203) 566-300	5			DISTRICT	IF NR.	SPECIFY	
٢					<u>s</u> Пи	R Actu	al Potential	
	1. BUILDING NAME (Common)		(Hist					
ļ	2. TOWN/CITY	VILLAGE	Dr	. J. Por	ter Hous			
z	Southington	-	р. СТ	06489	Hartf			
Ë	Southington Southington, CT 06489 Hartford 3. STREET AND NUMBER (and/or location) 391							
2	Belleview Ave. (map 73)	, parcel 59) 3 a	cres			·	
E	4. OWNER(S)	Polloviov	ANO (vol. 346.	p.825)	Public	X Private	
DENTIFICATION	Edgerly, Margaret L., 391	Delleview	(Histo	ric)	P.0207			
=	Residential Residential							
	ACCESSIBILITY EXTERIOR VISIBLE FROM PUBLIC RC		X No	IF YES, EXF				
	TO PUBLIC: Yes No 7. STYLE OF BUILDING	Yes	No		DATE OF CO	NSTRUCTION		
	Colonial				1728 A	. c. 175	4 (undated	
	Colonial 8. MATERIAL(S) (Indicate use or location when appr			0 ther		use tour		
	X Clapboard Asbestos Siding	Brick	c i i i i i i i i i i i i i i i i i i i	(Specify)			
	Wood Shingle Asphalt Siding	Field	dstone					
			0310116					
	Board & Batten Stucco	Сорр	Cobblestone					
	Aluminum Concrete	Cut :	X Type: Ashlar foundations					
	Siding . Type: X Type: <u>ASHIAT LOUNGALIONS</u>							
Ć	Wood frame X Post and beam	on						
	Load bearing masonry Structural iron or steel							
	Other (Specify)							
	10. ROOF (Type)							
	X Gable Flat Man	sard Monit	tor	sawtootl	ו			
	Gambrel Shed Hip	Roun	d	Other (Specify	.)			
DESCRIPTION					/ . <u></u>			
T I	(Material)							
SCR	X Wood Shingle Asphalt Tin	L Slate						
DE	Asphalt shingle Built up Tile	Other (Spec						
	11. NUMBER OF STORIES APPROXIMATE DIMENS							
	2 31 x 36' 12. CONDITION (Structural) (Exterior)							
			ר				d	
	Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated							
	X On original Moved N.A. X Yes No Greek Revival portico added							
	14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES							
	Barn Shed X Garage Other landscape features or buildings (Specify)							
	Carriage Garden							
	15. SURROUNDING ENVIRONMENT							
Open land Wood- Indus- Scattered buildings visible from site Commercial Indus- Indus- Rural High building density 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS The house faces west on a large let at a busine intervene time								
	The house faces west on a large lot at a busy intersection.							

	17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (Interior and/or exterior)							
DESCRIPTION (Continued)	The 5-bay front elevation of this large house has central doorway with side lights. Windows are 6/6. The second floor overhangs the first on the front and sides while the third floor overhangs the second on the ends. The central brick chimney is large. The plain entablature of the portico is supported by Greek Ionic fluted columns. The interior has five fire- places, original paneling, stairway and cupboard, according to notes for a house tour.							
	18. ARCHITECT							
	19. HISTORICAL OR ARCHITECTURAL IMPORTANCE							
	The house is architecturally significant as an excellent example of the Colonial style, with few alterations. The Greek Revival portico is an addition of historic significance.							
SIGNIFICANCE	The house is historically significant because it was the home of Dr. Joshua Porter, "one of the largest landholders and slave owners" in the town. Dr. Porter brought his bride to this house, probably already standing, in 1754.							
	(
SOURCES	Notes for a house tour to benefit Grace Methodist Church, nd. Directory of Southington's Old Homes, Southington Historical Society, n.d. 1988 site visit by Margaret Anderson of the Southington Historical Society							
	PHOTOGRAPHER							
РНОТО	David Ransom 11/85							
РНС	Northeast V-2							
BΥ	David Ransom 9/85							
ED	ORGANIZATION							
COMPIL	ADDRESS 33 Sunrise Hill Drive							
-	West Hartford, CT 06107							
20. 9	20. SUBSEQUENT FIELD EVALUATIONS							
1988: This house currently retains some of its paneling, its original staircase, and four of								
its fireplaces, one of which has a beehive oven. There are also wide board floors in some rooms.								
21. THREATS TO BUILDING OR SITE								
X None known Highways Vandalism Developers Other								
	Renewal Private Deterioration Zoning Explanation							