



Name: The Richards Mansion  
*Sussex Co.*  
Location: Georgetown, Delaware  
Dick Carter  
Photographer:  
Date: September, 1978  
Location of Negative: Hall of Records, Dover, DE  
Description: Front of house facing The Circle

Photograph Number: One of 13

*DOE*  
JUL 26 1979

JUN 19 1979



L.W. AGENCY  
By Appointment  
WALTER J. CLARK, CIO

GEORGETOWN  
TICKET AGENCY  
DAVID D. TIDWELL

LAW OFFICES  
OF  
HOWARD TENNIS &  
FIDUA GRAVES

INVESTMENT SECURITIES  
WILLIAM W. HILLER &  
DANIEL D. TIDWELL

Name: The Richards Mansion (S-132)  
*Sussex Co.*  
Location: The Circle and N. Bedford St.; Georgetown,  
Del.  
Photographer: Dick Carter  
Date: Sept, 1978  
Location of Negative: Hall of Records, Dover, DE  
Description: Side of front section of house facing  
North Bedford Street

Photograph Number: Two of 13

*DOIE*  
JUL 26 1979

JUN 19 1979



Name: The Richards Mansion (S-132)  
The Circle and North Bedford Street;  
Location: Georgetown, Delaware  
Photographer: Dick Carter *Sussex Co.*  
Date: Sept., 1978  
Location of Negative: Hall of Records, Dover, DE

Description: Rear of house on N. Bedford St. side showing  
Greek Revival front section with later Victorian add-  
itions, and remaining portion of 1790's house at rear  
with lowered roof and 19th century porch addition.

Photograph Number:

Three of 13

*DOE*  
JUL 26 1979

JUN 19 1979



Name: The Richards Mansion (S-132)  
Location: The Circle and N. Bedford St., Georgetown, DE  
Photographer: Dick Carter *Sussex Co.*  
Date: Sept., 1978  
Location of Negative: Hall of Records, Dover, DE  
Description: Southwest side of rear section of the house.  
Portion of Greek Revival section is visible  
at right. Small Milk House and larger shed  
are visible at left.

Photograph Number: Four of 13

*DOE*  
JUL 26 1979

JUN 19 1979



Name: The Richards Mansion (S-132)

*Sussex Co.*

Location: The Circle and N. Bedford St., Georgetown, DE

Photographer: Dick Carter

Date: Sept., 1978

Location of Negative: Hall of Records, Dover, DE

Description: Detail of northeast corner of main section showing blending of Greek Revival and Victorian details, including modified mansard roof and bay window.

Photograph Number: Five of 13

*DOE*

JUL 26 1979

JUN 19 1979



Name: The Richards Mansion (S-132)

*Sussex Co.*

Location: The Circle and N. Bedford St., Georgetown, DE

Photographer: Dick Carter

Date: Sept., 1978

Location of Negative: Hall of Records, Dover, DE

Description: Detail showing typical window of main section  
of house (this one on the southwest side,  
first floor)

Photograph Number: Six of 13

JUL 26 1979  
*DOE*

JUN 19 1979



Name: The Richards Mansion (S-132)

*Sussex Co.*

Location: The Circle and N. Bedford St., Georgetown, DE

Photographer: Dick Carter

Date: Sept, 1978

Location of Negative: Hall of Records, Dover, DE

Description: Detail showing one of original windows in rear (1790's) wing of house. Note: paneled shutters have board and batten exteriors. Shutter rests against wall of pantry added

Photograph Number: in 19th century.

Seven of 13

JUL 26 1979  
DOE

JUN 19 1979



Name: The Richards Mansion (S-132)  
Location: The Circle and N. Bedford St., Georgetown, DE  
*Sussex Co.*  
Photographer: Dick Carter  
Date: Sept., 1978  
Location of Negative: Hall of Records, Dover, DE  
Description: Detail of southwest side of house showing original wide horizontal beaded weatherboards of old section at left and narrower weatherboard siding of 19th century section at right. Note base of corner pilaster in center.  
Photograph Number: Eight of 13

JUL 26 1979  
*DOE*

JUN 19 1979



Name: The Richards Mansion (S-132)  
The Circle and N. Bedford St., Georgetown, DE  
Location: *Sussex Co.*  
Photographer: Dick Carter  
Date: Sept., 1978  
Location of Negative: Hall of Records, Dover, DE

Description: Detail of shed at southwest side of property  
showing door strap hinges and modern asbestos  
shingle siding (over original weatherboards)

Photograph Number: Nine of 13

JUL 26 1979  
DOE

JUN 19 1979



Name: The Richards Mansion (S-132)  
Location: The Circle and N. Bedford St., Georgetown, DE  
*Sussex Co.*  
Photographer: Dick Carter  
Date: Sept., 1978  
Location of Negative: Hall of Records, Dover, DE

Description: View of original Federal mantelpiece and  
cupboard in what is now the kitchen of the house  
in 18th century section.

Photograph Number: Ten of 13

*DOE*  
JUL 26 1979

JUN 19 1979



Name: The Richards Mansion (S-132)  
*Sussex Co.*  
Location: The Circle and N. Bedford St., Georgetown, DE  
Dick Carter  
Photographer:  
Date: Sept., 1978  
Location of Negative: Hall of Records, Dover, DE  
Description: Detail of Federal mantle in original  
section of house.

Photograph Number: Eleven of 13

*DOE*

JUL 26 1979

JUN 19 1979



Name: The Richards Mansion (S-132)

Location: The Circle and N. Bedford St., Georgetown, DE  
*Sussex Co.*

Photographer: Dick Carter

Date: Sept., 1978


Location of Negative: Hall of Records, Dover, DE

Description: View of second floor bedroom in old section  
of house showing original beaded beams,  
beaded board ceiling, and window trim.

Photograph Number: Twelve of 13

*DOE*  
JUL 26 1979

JUN 19 1979



Name: The Richards Mansion (S-132)  
Location: The Circle and N. Bedford St., Georgetown, DE  
*Sussex Co.*  
Photographer: Dick Carter  
Date: Sept., 1978  
Location of Negative: Hall of Records, Dover, DE  
Description: Detail showing gaslight fixture in third floor hallway of front section of house

Photograph Number: Thirteen of 13

*DOE*  
JUL 26 1979

JUN 19 1979