

MORRISTOWN, ERIE-LACKAWANNA

MORRIS

MORRISTOWN LINE

Build 1913

Delaware Jackawannant Western Railrood Station Morristown Railroad Station Morristown, New Jersey Photographed by B. Markowicz, February 1979 Negative: Transportation Program. Engineering Quad., Princeton University Morris County Western facade on the west side of the tracks, taken from the southwest, showing principal building and gate pillar. MAR 1 1 1980 JAN 1 4 1980




Delaware Lackow want Western Road 201 d St. Atton Morristown Railroad Station Morristown, New Jersey Photographed by B. Markowicz, April 1979 Negative: Transportation Program, Engineering Quad., Princeton University Western facade on the west side of the tracks, taken from the northwest, showing the waiting room and the marquise. MAR 1 1 1980 IAN 1 4 1980



aware Jackawanna tubeton Railrood Station Morristown Railroad Station Morristown, New Jersey Photographed by B. Markowicz, April, 1979 Negative: Transportation Program, Engineering Quad., Princeton University Eastern side of the tracks (western facade) and platform taken from the southwest. MAR 11 1980 Morris Const











MORRISTOWN

Delaware Lackowand to Stern Las Iroad Station Inoristom Railroad Str. Photographed by B. Markowicz, February 1979 Negative: Transportation Program. Engineering Quad., Princeton University View of the inside looking North. MAR 11 1980 JAN 1 4 1980