

Grimes Family House & Mill Complex Lexington Fayette County, Kentucky Antiques, March 1974 Helga Photo Studio

Photo 1 - North facade.



Bettie L. Kerr 253 Market Street, Lexington, Kentucky October, 1980

Photo 2 - Grimes Family House, looking southeast.




Bettie L. Kerr 253 Market Street, Lexington, Kentucky October, 1980

Photo 3 - East side of Grimes Family House looking west.



Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 4 - Eared door frame of present back of house, looking north.



Beebe Park (2000) 253 Market Street, Lexington, Ky. July, 1979

Photo 5 - Ell before recent remodeling, looking northeast.



Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 6 - Ell in process of remodeling, looking northwest.



Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 7 - Staircase in Grimes Family house



Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 8 - Staircase railing of Grimes House showing engaged post.




Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 9 - East interior wall of living room - Grimes Family House




Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 10 - Twentieth century barn, looking north



Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 11 - Grimes Mill looking southeast



Bettie L. Kerr 253 Market Street, Lexington, Ky. October, 1980

Photo 12 - Spring on Grimes Family House and Mill Co Complex property looking north.