

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont

Credit: Hugh H. Henry

Date: June, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Complex seen from New Hampshire
Route 12; (R-L) Buildings #2, 3, 7, 8, 10,
11, East, North elevations; View looking
Southwest
Photograph 1

82-A-37




82-A-37

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry

Date: June, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Complex seen from New Hampshire
Route 12; Buildings #7-12, South, East ele-
vations; View looking Northwest
Photograph 2




82-A-37

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: (R-L), Buildings #1, #2; beyond
canal forebay; View looking East
Photograph 3



Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Building #1, West elevation;
View looking Southeast
Photograph 4



Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Building #1, South elevation;
View looking East
Photograph 5

82-A-37



82-A-37

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Building #1, canal intake on
South elevation; View looking North
Photograph 6



82-A-37

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Building #2, West elevation;
View looking Northeast
Photograph 7



Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont

Credit: Hugh H. Henry

Date: June, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: (R#L) Buildings #2, 3, 7, North
elevation; View looking South

Photograph 8



Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: (R-L), Buildings #3, 7, 8, 10,
North elevation; View looking Southeast
Photograph 9

82-A-37



82-A-37

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Bag Shop, East wing, garage,
Northwest elevation View looking Southeast
Photograph 10



82-A-37

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: June, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Bag Shop, Northwest elevation;
View looking East
Photograph 11

82-A-232

Moore and Thompson Paper Mill Complex
Bellows Falls, Town of Rockingham, Vermont
Credit: Hugh H. Henry
Date: September 1982
Negative filed at Vermont Division for
Historic Preservation
Description: Detail of 1919 Survey
drawing of Moore and Thompson Paper
Company
Photograph 12