



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC  
ZACHARY TAYLOR HOME, "SPRINGFIELD"

AND/OR COMMON  
"Springfield"

**2 LOCATION**

CITY, TOWN  
Louisville

\_\_\_\_ VICINITY OF

STATE  
Kentucky

COUNTY  
Jefferson

**3 PHOTO REFERENCE**

PHOTO CREDIT  
Polly M. Rettig, Landmark Review Project

DATE OF PHOTO  
September 1975

NEGATIVE FILED AT  
Historic Sites Survey, Washington, D.C., National Park Service, 110

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

2

South (rear) elevation, showing tornado damage.



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

ZACHARY TAYLOR HOME, "SPRINGFIELD"

AND/OR COMMON

"Springfield"

**2 LOCATION**

CITY, TOWN

Louisville

VICINITY OF

STATE

Kentucky

COUNTY

Jefferson

**3 PHOTO REFERENCE**

PHOTO CREDIT

Polly M. Rettig, Landmark Review Project

DATE OF PHOTO

September 1975

NEGATIVE FILED AT

Historic Sites Survey, National Park Service, 1100 L St., N.W., Washington, D.C.

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 1

East and north (front) elevations, showing tornado damage.