Clarendon

DATA SHEET

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE PHO35 WOL

NATIONAL REGISTER OF HISTORIC PLACES INIVENITODY MOMINIATION FORM

FOR NPS USE ONLY

RECEIVED JUN 2 9 1976

_____ JUL 3 0 1976

Arkansas

		V TO COMPLETE NATIO COMPLETE APPLICA		
NAME		Code as good leady LOVE		,
HISTORIC				gent -
**	Cumberland Presbyteria			
AND/OR COM	MON Presbyteria	in Church		
		ld Masonic Lodge	unase improportants	CONTACTOR OF THE PARTY OF THE P
LOCAT	TION			
STREET & NUI	MBER			
	120 Washington Street		NOT FOR PUBLICATION	
CITY, TOWN			CONGRESSIONAL DISTR	ІСТ
STATE	Clarendon	VICINITY OF CODE	First	CODE
STATE	Arkansas	05	Monroe	095
CLASS	IFICATION	Helevos ens Loc	wa en chu 10we cu	
CATEG	ORY OWNERSHIP	STATUS	PRES	ENT USE
_DISTRICT		XOCCUPIED	AGRICULTURE	_MUSEUM
XBUILDING		UNOCCUPIED	COMMERCIAL	PARK
_STRUCTUR	REBOTH	WORK IN PROGRESS	EDUCATIONAL	PRIVATE RESIDENCE
SITE	PUBLIC ACQUISITIO		ENTERTAINMENT	RELIGIOUS
_OBJECT	IN PROCESS	XYES: RESTRICTED	GOVERNMENT	SCIENTIFIC
	BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL	_TRANSPORTATION
	To havened end eat print	_NO	MILITARY	XOTHER: Hall
OWNE	R OF PROPERTY			
NAME Tro	oop Committee of Troop 28			
NAME Tro				
NAME Tro	WBER and their successors Clarendon	s as Trustees for Tr	coop 28, Clarendon,	Monroe Co.
NAME Tro	Clarendon Clon OF LEGAL DESC	as Trustees for Tr	coop 28, Clarendon,	Monroe Co.
Tro STREET & NUM CITY, TOWN LOCAT COURTHOUSE REGISTRY OF STREET & NUM	Clarendon Clon OF LEGAL DESC	as Trustees for Tr	coop 28, Clarendon, STATE Arkansa	Monroe Co.
Tro STREET & NUR CITY, TOWN LOCAT COURTHOUSE REGISTRY OF	Clarendon Clon OF LEGAL DESC DEEDS,ETC. Monroe County County	as Trustees for Tr	coop 28, Clarendon,	Monroe Co.



_FAIR

CONDITION

__EXCELLENT __DETER __GOOD __RUINS

__DETERIORATED

UNEXPOSED

_UNALTERED

CHECK ONE

CHECK ONE

_ORIGINAL SITE
_MOVED DATE_____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Construction of the Cumberland Presbyterian Church was begun in 1869 and completed in July 1870. The bronze bell is thought to have been installed in 1887 and the sidewalk and approach was built in 1905 by Graham and Boardly at a cost of $12\frac{1}{2}$ cents per foot.

The architectural significance lies not so much in the strict adhermence to a particular style, as in the sturdiness of construction-being built to last rather than to impress.

The roof is of a low pitch, with gables at the front and rear. The generous but plain cornice is carried across the gable at the front in the Greek Revival style. The exterior walls are of white clapboards, lapped with 5" width exposed. The windows are regularly spaced with small panes, and with simple straight facings and moldings. Windows on the lower floor are covered with exterior louvered shutters.

Unadorned square posts, not freestanding, support the arched opening to the projected entrance. This projection extends out and upward beyond the second story forming the bell tower (now lowered) originally to a height of over thirty (30) feet. The tower was in 3 sections; the first with a half-circle window, the second with a round window and the third which housed the bell had louvered openings on four sides. The belfry was topped with a hip roof. The only change in the original exterior of the building was the removal of the upper section of the bell tower in about 1940. After being damaged in a storm, it was cut down to the level of the main roof.

The exterior is in need of repairs, window pane replacements and paint.

The engraved letters CPC are still plainly visible in the concrete steps leading to the entrance, although a part of the steps which at one time had the date 1869 has crumbled away.

The same spirit of simplicity is carried out in the interior. Two thirty-six (36) inch six-paneled doors, with rectangular transom above, open into a spacious vestibule. A small room is to the right and the open stairway with plain banister is on the left. The original stairs, which were much steeper, have been replaced and it can easily be determined on the wall where the first ladder-like stairway was attached.

From the vestibule, two thirty-six (36) inch glass doors (with single large pane in each) open into the sanctuary which comprises the rest of the lower floor. Four round Doric columns reach from the floor to the high ceiling, two on either side of the aisle. Only a few pews survived the 1927 flood, and were not replaced, as the building was at that time no longer used for worship services. All other fixtures were removed when the lower floor was used as a library. All of the

Form No. 10-300a

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS USE ONLY

RECEIVED

JUN 2 9 1976

DATE ENTERED

JUL 3 0 1976

CONTINUATION SHEET

ITEM NUMBER 7

PAGE one

interior walls are of the original plaster over wooden lathing. The floors are of irregular width boards of from four (4) inch to six (6) inch, and all appear to be the originals. Two narrow chimneys are placed in the middle of each side of the interior. Wood stoves were originally used, now replaced by gas.

The upper floor, which was used for the Masonic Hall, has the same basic floor plan. There are interior louvered shutters on the lower half of the upper windows. On a raised platform at the rear of the large room, there are two square Doric columns supporting an arch, all of which is of good workmanship.

The very best timber was used in the framework of the building. The floor sills are of twelve (12) inch square heart-cypress timbers, hewn and interlocked tightly together around the edge of the building and running down the center from front to back. The floor joists are of twelve (12) inch by about one-and-one-half ($1\frac{1}{2}$) inch cypress sawed boards, closely spaced, with bridging between. The foundation is of closely spaced brick piers, about two-and-one-half (21/2) feet high. In the outside walls the studs are of 2 X 4's, spaced every twelve (12) inches with fire walls made of 2 X 4's between the studs every four (4) feet. Each of the four (4) foot sections are braced with crossed 2 X 4's. These sections have made a perfect home for honey bees and have never been successfully removed. This type of wall construction is also the most unusual feature of the building. The beams are of hewed heart-cypress, interlocked tightly and with the use of wooden pegs. All of the timbers are in excellent condition, with no signs of rotting, shifting or damage. The walls, floors, plumbing and electrical wiring is in need of repair.

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW PERIOD _LANDSCAPE ARCHITECTURE X_RELIGION _ARCHEOLOGY-PREHISTORIC X_COMMUNITY PLANNING __PREHISTORIC _LAW _ARCHEOLOGY-HISTORIC __CONSERVATION _SCIENCE __1400-1499 _AGRICULTURE _ECONOMICS LITERATURE _SCULPTURE _1500-1599 _MILITARY _SOCIAL/HUMANITARIAN _1600-1699 *_ARCHITECTURE X_EDUCATION FNGINEERING __MUSIC __THEATER _1700-1799 _ART _EXPLORATION/SETTLEMENT _PHILOSOPHY _TRANSPORTATION __COMMERCE X1800-1899 _INDUSTRY __POLITICS/GOVERNMENT _OTHER (SPECIFY) 1900-__COMMUNICATIONS _INVENTION

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The many ways in which this building has been used exemplifies how a small community can work together in cooperative fellowship, so that the lives of the citizens, both young and old, will be spiritually and educationally enriched. With its sturdy construction and simple but dignified style, it is a typical example of the type of church buildings that were erected during a period of hardship and struggle, by citizens who realized the importance of having a place for worship.

The town of Clarendon was completely destroyed by shelling and burning in June, 1864, forcing the evacuation of the town. The people returned after the close of the Civil War to rebuild their homes and businesses from the weeds and ashes. It is significant that during this time of struggle to return to their former way of life that the spiritual needs of the community were realized by the erection and cooperative use of this church building. The fact that it has survived through numerous floods and many years of weathering and still useful, testifies to the sturdiness of construction.

The original deed to the property, dated September 15, 1869 was to the Cumberland Presbyterian Church of Clarendon, and stated that the use of the church was to be freely offered to other denominations when not in use by the Cumberland Presbyterians. The July 9, 1870 minutes of the session state "it was resolved to tender the use of the new Church House now nearly completed, to the Methodist Episcopal Church South, The Presbyterian Church and the Baptist Church, each a portion of the time when not used by the Cumberland Presbyterians." On July 16, 1870 the session resolved to hire a sexton and request the other denominations worshipping in the house to bear equal parts of the sexton's hire. Thus the building was completed and several congregations were using the building by this date.

Not only was the building constructed for use by several religious groups, but it is also thought that it was erected jointly by the Cumberland Presbyterians and the Cache Lodge 235 of Free Masons, whose group was organized November 20, 1869, and whose members state that they used the upper floor of the church from the time of its erection until they sold the building in 1968.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Record Books of the Clarendon Congregation, Cumberland Presbyterian Church Charter of Cache Lodge 235 of Free Masons, Clarendon, Ark.

Scrapbooks containing newspaper articles about interviews with former members living in Clarendon when the building was erected; articles also about the Clarendon Library and the 1927 Flood.

Monroe County Deed Records.

Now I										
10	GE	α	DA	m	TTC	AT	D	A	T	A
ш	TT.	UNT	K A	(PI				A	1 /	1
The Real Property lies	~~							-		-

ACREAGE OF NOMINATED PROPERTY less than one acre

UTM REFERENCES

A 1 5	6 5 4 6 10 10	3840	в , 1	11,1,,	11.1
ZONE	EASTING	NORTHING	ZONE	EASTING	NORTH
C			D	LILIT	

VERBAL BOUNDARY DESCRIPTION

East half (80 feet) of lot five (5) Block two (2) Original Town of Clarendon.

LIST ALL STATES AND	COUNTIES FOR PROPERTIES	OVERLAPPING	STATE OR COUNTY	/ BOUNDARIES
---------------------	--------------------------------	--------------------	-----------------	--------------

STATE CODE COUNTY CODE STATE CODE COUNTY

II FORM PREPARED BY

NAME / TITLE

Jo Claire English, research historian,

ORGANIZATION Monroe County Historical Society March 18, 1976 STREET & NUMBER TELEPHONE P.O. Box 206 (501) 747-3963 or 747-3311 CITY OR TOWN STATE

Clarendon Arkansas

2 STATE HISTORIC PRESERVATION OFFICER CERTIFICATION

THE EVALUATED SIGNIFICANCE OF THIS PROPERTY WITHIN THE STATE IS:

LOCAL V NATIONAL ____ STATE____

As the designated State Historic Preservation Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service.

STATE HISTORIC PRESERVATION OFFICER SIGNATURE Anne Bartlev

DATE 6-8-76

TITLE State Historic Preservation Officer FOR NPS USE ONLY

I HEREBY CERTIFY THAT THIS PROPERTY IS INCLUDED IN THE NATIONAL REGISTER

7.30 VE DATE

DIRECTOR, OFFICE OF ARCHEOLOGY AND HISTORIC PRESERVATION

DATE

CLUKEEPER OF THE NATIONAL REGISTER

Form No. 10-300a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR NPS USE ONLY

RECEIVED

JUN 2 9 1976

DATE ENTERED

JUL 3 0 1976

CONTINUATION SHEET

ITEM NUMBER

8

PAGE

one

The Cumberland Church had been organized in 1857, according to an entry in the record books, and records are intact from March 1869-1920. In 1920, the Cumberland Presbyterian Church united with the First Presbyterian Church of Clarendon and from that time the Masons became the sole owners of the building.

From an entry under building expense it is determined that the congregation paid \$2500.00 for the building. If the Masons shared jointly in the expense, the total cost was probably \$5000.00. This joint ownership would also explain the reason for a two-story building.

After the lower floor was vacated by the congregation, the Masons allowed the lower floor to be used for various community purposes. The Clarendon Library was housed there for about 20 years. It was operated by librarians who worked without pay, and part of this time was sponsored by Civic organizations. Nearly 4,500 volumes of books were damaged or destroyed when the lower floor was submerged during the 1927 Flood. After the break in the Clarendon Levee, the church withstood the rush of the water without structural damage.

The W.L. Boswell Chapter of the Order of the Eastern Star also held their meetings in the building. At one time a kindergarten was held there, and a teen-age club met in the building for a short time. It was about the year 1960 that the Masons allowed the Boy Scouts to use the lower floor for their meeting place, which they have done since that time.

In 1968 when Cache Lodge 235 decided to tear down the building to erect a new lodge hall. Mrs. W. F. Vaughan, to prevent the destruction of the church, donated the necessary funds to the Troop Committee of the Boy Scout Troop 28, and with the funds they purchased the building. Thus the Boy Scouts are the present owners and occupy the building for their "Scout Hall".

Thus the old church, whose cornerstone was laid in 1869, which was built for service to the community's spiritual life, has served in many worthwhile areas—all of which have been for the betterment of the community. It has defied going out of service, having served continuously, as no other building in Clarendon has served to so many worthy groups. It continues to stand, amid the tall oak trees, meeting the needs of today and of our future citizens as it did for those of the past.

Property	Cumberland	Presbyterian Church		
State	Arkansas	Working Number	6.29.76.3688	76000438
TECH				CONTROL
Pho Mag	otos <u>/</u> ps/_			Ot 21,76
				HISTORIAN
				accept
				3. Grovens
				7/2/74
			ARCHITEC	
				accept
				accept Soldham 7/6/76
				ARCHEOLOGIST
				OTHER
				HAER
				Inventory
				Review
			R	EVIEW UNIT CHIEF
				BRANCH CHIEF
				accept
				Cole
				7-6-76
				KEEPER
				Herry
				7.36.26
National	Register Write	-up s	end-back	Entered JUL 3 0 19/6
	Register Entry		e-submit	
	3			INT:2106-74

. MOPROF CO.



1. CUMBETIAND PRESBYTERIAND Church
monroe county, Arkansas

50 U

Form No. 10-301a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED JUN 2 9 1976

DATE ENTERED JUL 3 0 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Cumberland Presbyterian Church

AND/OR COMMON

2 LOCATION

CITY, TOWN Clarendon

___VICINITY OF

COUNTY Monroe

STATE Arkansas

3 PHOTO REFERENCE

PHOTO CREDIT Sandra Taylor

DATE OF PHOTO

April, 1976

NEGATIVE FILED AT Arkansas Historic Preservation Program

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

South and west elevations, viewed from the southwest

РНОТО NO.

1

INT: 2983-75



2. CUMBERIAND PRESBYTERIAN Church MONTOE COUNTY ANKANSAS

Form No. 10-301a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

JUN 2 9 1976

JUL 8 0 1976

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Cumberland Presbyterian Church

AND/OR COMMON

2 LOCATION

CITY. TOWN Clarendon

__VICINITY OF

COUNTY Monroe

STATE Arkansas

3 PHOTO REFERENCE

PHOTO CREDIT Sandra Taylor

DATE OF PHOTO April, 1976

NEGATIVE FILED AT Arkansas Historic Preservation Program

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

South and east elevations, viewed from the southeast

РНОТО NO.

2

INT: 2983-75

LIBRALL SILES ALLES ON A STATE OF THE STATE



3. CUMBERLAND PresbyteriAN Church MONTOE COUNTY, ACKANSAS south clanation mitules from the Form No. 10-301a

(Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

JUN 2 9 1976

DATE ENTERED

JUL 3 0 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

NAME

HISTORIC

Cumberland Presbyterian Church

AND/OR COMMON

LOCATION

CITY, TOWN Clarendon

_VICINITY OF

Monroe COUNTY

STATE Arkansas

PHOTO REFERENCE

PHOTO CREDIT Sandra Taylor

April, 1976 DATE OF PHOTO

NEGATIVE FILED AT Arkansas Historic Preservation Program

IDENTIFICATION


DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET South elevation, viewed from the south

PHOTO NO

3

INT: 2983-75

PROPERTY OF THE NATIONAL REGISTER



4. Cum BERTAND PRESBYTERIAN Church monroe (ounty, Arkansas interior, facing North L. r. e, 7/30/76



Form No. 10-301a (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTER NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

RECEIVED JUN 2 9 1976

DATE ENTERED JUL 3 0 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Cumberland Presbyterian Church

AND/OR COMMON

2 LOCATION

CITY, TOWN Clarendon

__VICINITY OF

COUNTY Monroe

STATE Arkansas

3 PHOTO REFERENCE

PHOTO CREDIT Sandra Taylor

DATE OF PHOTO April, 1976

NEGATIVE FILED AT Arkansas Historic Preservation Program

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET Interior, facing north

PHOTO NO.

INT: 2983-75

Form No. 10-301 (Rev. 10-74)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY MAP FORM

FOR NPS USE ONLY
RECEIVED JUN 2 9 1976

DATE ENTERED JUL 3 0 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH MAP

1 NAME

HISTORIC

Cumberland Presbyterian Church

AND/OR COMMON

2 LOCATION

CITY. TOWN Clarendon

___VICINITY OF

COUNTY Monroe

STATE Arkansas

3 MAP REFERENCE

SOURCE

USGS, Clarendon Quadrangle

SCALE

1:24,000


DATE 1968

4 REQUIREMENTS

TO BE INCLUDED ON ALL MAPS

- 1. PROPERTY BOUNDARIES
- 2. NORTH ARROW
- 3. UTM REFERENCES

INT: 2986-75



ENTRIES IN THE NATIONAL REGISTER

STATE

ARKANSAS

Date Entered

JUL 3 0 1976

Name

Location

Cumberland Presbyterian Church

Clarendon Monroe County

Logan County Courthouse, Eastern District

Paris Logan County

Mount Olive United Methodist Church

Van Buren Crawford County

Also Notified

Hon. John L. McClellan Hon. Dale Bumpers Hon. Bill Alexander

Hon. John P. Hammerschmidt

Regional Director, Southwest Region

MMott/row

PR

8/4/76

State Historic Preservation Officer
Ms. Anne Bartley
Acting Director
Department of Natural and
Cultural Heritage
The Old State House
300 West Markham
Little Rock, Arkansas 72201

NR Data Sheet

Claims

"first" YES

DATE: 7/2/74
Reviewer INITIALS: 86

DOEL JUL 3 0 1976

NAME AS IT APPEARS IN FEDERAL REGISTER: Cumberland Peesbyterian Church OTHER NAMES: Boy Scout Hall; Old Masonic Lodge -LOCATION: STREET & NUMBER 120 Washington St. 1st Clarendon CONGRESSIONAL DISTRICT VICINITY OF STATE Arkansas 05 code COUNTY 095 Monroe OWNER OF PROPERTY: (Circle) (PRIVATE) STATE LOCAL GOV'T MUNICIPAL COUNTY FEDERAL (AGENCY NAME): ADMINISTRATOR (underline) NPS REGION: (CIRCLE) N.ATLANTIC MID ATLANTIC SOUTHEAST SOUTHWEST ROCKY MOUNTAIN PACIFIC NORTHWEST WEST FEATURES: EXTERIOR ENVIRONS Substantially intact-2 Substantially intact-3 Substantially intact-1 _.unknown -6 _ unknown - 4 unknown.-5 _ not applicable - 8 not applicable - 7 _Not applicable-9 _Interior, exterior, environs not intact-0 WNALTERED __DETERIORATED _ORIGINAL SITE CONDITION -ALTERED _RUINS _G000 MOVED _Reconstructed _Unknown FAIR __UNEXPOSED _Unexcavated _Excavated Yes-restricted Yes-unrestricted No access Unknown historic district? NO WITHIN NATIONAL REGISTER HISTORIC DISTRICT? IF YES, NAME: WITHIN NATIONAL HISTORIC LANDMARK? NO IF YES, NAME: ADAPTIVE USE: YES Saved? YES FUNCTION(S): (use vocabulary words) thennow-**SIGNIFICANCE:** _LANDSCAPE ARCHITECTURE LA RELIGION ARCHEOLOGY-PREHISTORIC entertainment ARCHEOLOGY HISTORIC _CONSERVATION _LAW/Gov't/politics _science _health AGRICULTURE ECONOMICS _LITERATURE _recreation ARCHITECTURE DEDUCATION _MILITARY _settlement ENGINEERING MUSIC 30/socio/cultural __COMMERCE EXPLORATION __PHILOSOPHY _TRANSPORTATION _urban & commun __COMMUNICATIONS INDUSTRY _POLITICS/GOVERNMENT _OTHER (SPECIFY) planning

ARCHITECTURAL STYLE: Eclectic

architect/m.builder:

landscape/garden designer:

interior decorator:

engineer: artist/artisan:

builder/contractor:

ETHNIC GROUP:

NAMES:

personal

(label role

appropriate date)

events

institutional

DATES: DATE OF CONSTRUCTION (Specific date or 1/4 of century): 1870

DATE(S) OF "MAJOR" ALTERATIONS: 1940

HISTORICALLY SIGNIFICANT DATE(S): 1869 - present

SOURCE: (OF NOMINATION)

LOCAL GOV"T MUNICIPAL

COUNTY

OTHER FEDERAL AGENCY:

ACREAGE: (to nearest tenth of an acre)

COMMENTS: (include architectural information here)

port center town were received round-arched portal and and galled Juli area; decreed to say buel about 1940 after being damaged in a cotorn unusual wall corner pilasters The sound set interior extensively aftered for variety

Edechi with sheek lewwal elements.

SIGNIFICANCE: (maximum two sentences) Built after founds

· Clerendon's destruction during the the me Masons, a bloary,