NESS NML, CROW CREEK MINE



SEP 1 3 1978

Grow Creek Mine ANGR 29 1978 Auchorg JE CMAR 29 1978 1. Original Manager's residence, in recent years, the Mess Hall. Looking North. 10-1-77 Michael Carberry, Anc. Hist. Landmarks Pres. Comm., Pouch 6-650. Anchorage, Ak. 99501

MANAGER'S HANSE, CROW CREEK MINE



SEP 15 1978

Crow Creek Mine, ANC-129

2. Present Manager's residence Looking Northeast Looking Northeast 12

Michael Carberry, Ancora Landmarks Preservation Commiss. Municipal Planning Office, Pouch 6-650, Anchorage, Ak 99501



SEP 1 3 1978

Crow Creek Mine ANC-129 Auch ORAGE C 3. Kitchen in present Manager Residence. 10-1-7MAR 2 9 1978 Michael Carberry, Anchorage Hist Landmarks Preservation Commiss. Municipal Planning Office, Pouch 6-650, Anch., Ak., 99501



CROW CREEK MINE

SEP 1 3 1978

Grow MAR 2 9 19 Grow Creek Mine (ANG-129 Ancholde CD. 4. General view, left to right: Messhall, 2-man Bunk house, Tool shed(rear) and Commissary bldg. Michael Carberry, Hist. Landmarks Preservation Commission, Munic. Planning Office, Pouch 6-650, 5 Anchorage, Alaska 99501 407-5



SEP 13 1978

Crow Creek Mine ANC-129 5. Commissary. Ar honage Co. and shaked roof. MAR 29 1978 Michael Carberry, Historic Landmarks Preservation Commission, Municaipal Planning Office, Pouch, 6-650, Anchorage, Ak. 995015465