

Location; on Road 299, northwest of Middletown, DE Photographer; Ed Herbener's Post-Card & Music Shop Date: ?

Location of Negative, John M. Gibson,

Description: Box 76 Drumore, PA

Protograph Number: 1812 OCT 311977

N-106

NEW Costle Co.

7 197



Locations on Road 299, northwest of Middletown, DE

Photographer: Edward F. Heite

Date: April 1977

Location of Negative? Div. of Hist. & Cult. Affairs, Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:

Facade which faces west

Photograph Number: 2 & 🔾

N-106

Co.

OCT 31 1977

17 1978



Locations On road 299, northwest of Middletown, DE

Photographer: Edward F. Heite

Date: Apr.1977

Location of Negative? Div. of Hist. & Cult. Affairs, Bureau of Archaeology & Hist. Preserv., Dover, DE

Description: Detail of unusual cross gable.

Photograph Number:

3912

OCT 31 1977

N-106

NEW CASHE CO.

FEB 17 1978



Location: On road 299, northwest of Middletown, DE

Photographer: Jean Athan

Date: September 1977

Location of Negatives Div. of Hist. & Cult. Affairs, Bureau of Archaeology & Hist. Preserv., Dover DE

Description:

Detail of front door.

Photograph Number:

4312

T 311977

N-106

NEW CASHE CO.

17 1978



Location: On Road 299, Northwest of Middletown, DE

Photographer: Jean Athan
Date: September 1977

Location of Negatives Div. of Hist. & Cult. Affairs, Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:

East (rear) of house and north side of wing.

Photograph Number: 5A12

QCT 31 1977

N-106 FEB 1 7 1978



Location: On Road 299, northwest of Middletown, DE

Photographer: Jean Athan Date: September 1997

Location of Negatives Div. of Hist. & Cult. Affairs, Bureau of Archaeology & Hist. Preserv., Dover, DE

Description:

N-106

East wall (rear) of wing with shed.

Photograph Number:

6212

OCT 31 1977

New Costle



Location: On Road 299, northwest of Middletown, DE

Photographer: Jean Athan Date: September 1977

Location of Negatives Div. of Hist. & Cult. Affairs, Bureau of Archaeology & Hist. Preserv., Dover, DE Description:

South wall of wing showing bay window.

Numbers 7.19

Photograph Number: 78 💫 N-106

OCT 31 1977

Vew Costle Co. 17 1978



Location: On Road 299, northwest of Middletown, DE

Photographer Jean Athan

Date: September 1977

Location of Negatives Div. of Hist. & Cult. Affairs, Bureau of Archaeology & Hist. Preserv., Dover, DE Description:

Stair in central stairhall.

Photograph Number: 884

N-106

New Codle CEB 17 1978 OCT 31 1977



Location: On Road 299, northwest of Middletown, DE

Photographer: Jean Athan Date: September 1977

Location of Negative Div. of Hist. & Cult. Affairs, Bureau of Archaeology & HIst. Preserv., Dover, DE

Description:
Architrave common to all the doors and windows in the main section of the house.

Photograph Number: 95 (2

N-106

NEW CASHE CO. 31 1977

FEB 17 1978

N-106



Location: On Road 299, northwest of Middletown, DE

Photographer: Jean Athan Date: September 1977

Location of Negatives Div. of Hist. & Cult. Affairs,

Bureau of Archaeology & Hist. Preserv., Dover, DE Description:

Description:

Doorway and winding stair in the front section of the wing (dining room)

Photograph Number: 10812

N-106

New Castle Co. OCT 31 1977 FEB 17 1978



Location: On Road 299, northwest of Middletown, DE

Photographer Jean Athan Date: September 1977
Location of Negative:

Bureau of Archaeology & Hist Presery Doyer DF

Bureau of Archaeology & Hist. Preserv., Dover, DE Description:

Winding stair in the back section of the wing (Kitchen)

Photograph Number: 11312

OCT 311977

17 1978

NEW CASHE CO.



Location: On Road 299, northwest of Middletown, DE

Photographer: Jean Athan

Date: September 1977

Location of Negatives Div. of Hist. & Cult. Affairs, Bureau of Archaeology & HIst. Preserv., Dover, DE Description:

Original mantle in an upstairs bedroom.

Photograph Number: 12 A 12

N-106

NEW Conte Co.

OCT 31 1977 FEB 17 1978