




MCINTEER  
VILLA

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

*(Type all entries - attach to or enclose with photograph)*

|  |                 |  |
|--|-----------------|--|
| <b>1. NAME</b>                         |                 | <b>NUMERIC CODE</b> <i>(Assigned by NPS)</i>           |
| COMMON                                 | AND/OR HISTORIC |  |
|  | McInteer Villa  | MAR 26 1975  |
| <b>2. LOCATION</b>                     |                 |  |
| STATE                                  | COUNTY          | TOWN   |
| Kansas                                 | Atchison        | Atchison   |
| STREET AND NUMBER                      |                 |  |
| 1301 Kansas                            |                 |  |
| <b>3. PHOTO REFERENCE</b>              |                 |  |
| PHOTO CREDIT                           | DATE            | NEGATIVE FILED AT                                      |
| Staff, Kansas State Historical Society | Oct. 2, 1974    | Historic Sites Survey, Kansas State Historical Society |
| <b>4. IDENTIFICATION</b>               |                 |  |
| DESCRIBE VIEW, DIRECTION, ETC.         |                 |  |



Name plaque on north wall, from north, Detail work visible here is typical of what is found all over the exterior.

**PROPERTY OF THE NATIONAL REGISTER**

#1086




UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

*(Type all entries - attach to or enclose with photograph)*

|   |                 |   |
|---|-----------------|---|
| <b>1. NAME</b>                            |                 |   |
| COMMON                                    | AND/OR HISTORIC | NUMERIC CODE <i>(Assigned by NPS)</i>                     |
|   | McInteer Villa  | MAR 26 1975   |
| <b>2. LOCATION</b>                        |                 |   |
| STATE                                     | COUNTY          | TOWN  |
| Kansas                                    | Atchison        | Atchison  |
| STREET AND NUMBER                         |                 |   |
| 1301 Kansas                               |                 |   |
| <b>3. PHOTO REFERENCE</b>                 |                 |   |
| PHOTO CREDIT                              | DATE            | NEGATIVE FILED AT   |
| Staff, Kansas State<br>Historical Society | Oct. 2, 1974    | Historic Sites Survey, Kansas<br>State Historical Society |
| <b>4. IDENTIFICATION</b>                  |                 |   |
| DESCRIBE VIEW, DIRECTION, ETC.            |                 |   |



McInteer Villa, east entry, from east. Formerly a main entrance, now boarded up. The porch was removed many years ago.

**PROPERTY OF THE NATIONAL REGISTER**

# 296




UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

|  |                 |  |
|--|-----------------|--|
| 1. NAME                                |                 |  |
| COMMON                                 | AND/OR HISTORIC | NUMERIC CODE (Assigned by NPS)                         |
|  | McInteer Villa  | MAR 26 1975  |
| 2. LOCATION                            |                 |  |
| STATE                                  | COUNTY          | TOWN   |
| Kansas                                 | Atchison        | Atchison   |
| STREET AND NUMBER                      |                 |  |
| 1301 Kansas                            |                 |  |
| 3. PHOTO REFERENCE                     |                 |  |
| PHOTO CREDIT                           | DATE            | NEGATIVE FILED AT                                      |
| Staff, Kansas State Historical Society | Oct. 2, 1974    | Historic Sites Survey, Kansas State Historical Society |
| 4. IDENTIFICATION                      |                 |  |
| DESCRIBE VIEW, DIRECTION, ETC.         |                 |  |



McInteer Villa, east bay, from the east. Some of the building's ornamentation in stone, wood, glass and metal is evident in this view.

# 3 086

PROPERTY OF THE NATIONAL REGISTER



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

|                |                 |                                |
|----------------|-----------------|--------------------------------|
| <b>1. NAME</b> |                 |                                |
| COMMON         | AND/OR HISTORIC | NUMERIC CODE (Assigned by NPS) |
|                | McInteer Villa  |                                |

MAR 26 1975

|                    |          |          |
|--------------------|----------|----------|
| <b>2. LOCATION</b> |          |          |
| STATE              | COUNTY   | TOWN     |
| Kansas             | Atchison | Atchison |

**STREET AND NUMBER**


1301 Kansas

|  |              |  |
|--|--------------|--|
| <b>3. PHOTO REFERENCE</b>              |              |  |
| PHOTO CREDIT                           | DATE         | NEGATIVE FILED AT                                      |
| Staff, Kansas State Historical Society | Oct. 2, 1974 | Historic Sites Survey, Kansas State Historical Society |

**4. IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC.

McInteer Villa from southwest.



PROPERTY OF THE NATIONAL REGISTER

#486






SPEED  
LIMIT  
20

UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

|  |                 |  |
|--|-----------------|--|
| 1. NAME                                |                 |  |
| COMMON                                 | AND/OR HISTORIC | NUMERIC CODE (Assigned by NPS)                         |
|  | McInteer Villa  | MAR 26 1975  |
| 2. LOCATION                            |                 |  |
| STATE                                  | COUNTY          | TOWN   |
| Kansas                                 | Atchison        | Atchison   |
| STREET AND NUMBER                      |                 |  |
| 1301 Kansas                            |                 |  |
| 3. PHOTO REFERENCE                     |                 |  |
| PHOTO CREDIT                           | DATE            | NEGATIVE FILED AT                                      |
| Staff, Kansas State Historical Society | Oct. 2, 1974    | Historic Sites Survey, Kansas State Historical Society |
| 4. IDENTIFICATION                      |                 |  |
| DESCRIBE VIEW, DIRECTION, ETC.         |                 |  |



McInteer Villa from southeast, showing the building's most prominent feature, the tower at the southeast corner.

#5086

PROPERTY OF THE NATIONAL REGISTER




UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

*(Type all entries - attach to or enclose with photograph)*

|  |                 |  |
|--|-----------------|--|
| <b>1. NAME</b>                         |                 |  |
| COMMON                                 | AND/OR HISTORIC | NUMERIC CODE <i>(Assigned by NPS)</i>                  |
|  | McInteer Villa  | MAR 26 1975  |
| <b>2. LOCATION</b>                     |                 |  |
| STATE                                  | COUNTY          | TOWN   |
| Kansas                                 | Atchison        | Atchison   |
| STREET AND NUMBER                      |                 |  |
| 1301 Kansas                            |                 |  |
| <b>3. PHOTO REFERENCE</b>              |                 |  |
| PHOTO CREDIT                           | DATE            | NEGATIVE FILED AT                                      |
| Staff, Kansas State Historical Society | Oct. 2, 1974    | Historic Sites Survey, Kansas State Historical Society |



**4. IDENTIFICATION**  
DESCRIBE VIEW, DIRECTION, ETC.

McInteer Villa from northeast, showing some of the structure's major features: many dormers, corbeled brick chimneys and decorative window treatment.

**PROPERTY OF THE NATIONAL REGISTER**

#696