



First Congregational Church

Sioux Falls, South Dakota

Carolyn Torma

Historical Preservation Center

1983

South, side and front, east facades

Photo 1



First Congregational Church

Sioux Falls, South Dakota

Carolyn Torma

Historical Preservation Center

1983

Front platform and organ, facing west

Photo 2



First Congregational Church

Sioux Falls, South Dakota


Carolyn Torma

Historical Preservation Center

1983

Side, educational wing, looking northeast

Photo 3



First Congregational Church

Sioux Falls, South Dakota

Carolyn Torma

Historical Preservation Center

Interior, original window in lobby

1983

Photo 4



First Congregational Church

Sioux Falls, South Dakota

Carolyn Torma

Historical Preservation Center

1983

Light fixture, balcony

Photo 5



First Congregational Church
Sioux Falls, South Dakota
Carolyn Torma
Historical Preservation Center
1983
New windows in auditorium
Photo 6



First Congregational Church

Sioux Falls, South Dakota

Carolyn Torma

Historical Preservation Center

1983

original window, front facade

Photo 7



First Congregational Church

Sioux Falls, South Dakota

Carolyn Torma

Historical Preservation Center

1983

Rear, facade, Educational wing, looking east

Photo 10



First Congregational Church

Sioux Falls, South Dakota

Carolyn Torma

Historical Preservation Center

1983

Front facade, east side, Educational Wing

Photo 11