



Name: Jesse Robinson house

Location: High Street, Seaford, Sussex County, Delaware

Photographer: Richard B. Carter

Date of Photograph: December, 1980

Location of Negative: Bureau of Archaeology & Historic
Preservation, Dover, Delaware

Description: c. 1860 section from north-northeast

Photograph Number: 1 of 7



Name: Jesse Robinson house

Location: High Street, Seaford, Sussex County, Delaware

Photographer: Richard B. Carter

Date of Photograph: December, 1980

Location of Negative: Bureau of Archaeology & Historic
Preservation, Dover, Delaware

Description: c. 1820 section from south-southeast

Photograph Number: 2 of 7



Name: Jesse Robinson House

Location: High Street, Seaford, Sussex County, Delaware

Photographer: Richard B. Carter

Date of Photograph: December, 1980

Location of Negative: Bureau of Archaeology & Historic
Preservation, Dover, Delaware

Descripton: c. 1820 section from east

Photograph Number: 3 of 7



Name: Jesse Robinson House

Location: High Street, Seaford, Sussex County, Delaware

Photographer: Richard B. Carter

Date of Photograph: December, 1980

Location of Negative: Bureau of Archaeology & Historic
Preservation, Dover, Delaware

Description: view of rough floor joists under c. 1820
section

Photograph Number: 4 of 7



Name: Jesse Robinson house

Location: High Street, Seaford, Sussex County, Delaware

Photographer: Richard B. Carter

Date of Photograph: December, 1980

Location of Negative: Bureau of Archaeology & Historic
Preservation, Dover, Delaware

Description: view of enclosed cover stairway in c. 1820
section (flowered decoration in door panels
is contact paper)

Photograph Number: 5 of 7



Name: Jesse Robinson House

Location: High Street, Seaford, Sussex County, Delaware

Photographer: Richard B. Carter

Date of Photograph: December, 1980

Location of Negative: Bureau of Archaeology & Historic
Preservation

Description: view of second floor door and surround,

Photograph Number: c. 1860 section
6 of 7



Name: Jesse Robinson house

Location: High Street, Seaford, Sussex County, Delaware

Photographer: Richard B. Carter

Date of Photograph: December, 1980

Location of Negative: Bureau of Archaeology & Historic
Preservation

Description: view of mantelpiece, c. 1860 section

Photograph Number: 7 of 7