

Shady Lea Mill North Kingstown, RI

Photographer: Ellen Weiss

Date: 1978

Negative filed at: R.I. Historical Preservation Commission (EW 23:26)

Description: Mill from northeast.

Photo No.20

3

share



Shady Lea Mill North Kingstown, R.I.

Photographer: Charlene Roise

Date: July 1981

Negative filed at: R.I. Historical Preservation Commission (CKR 1:26)

Description: Mill dam and pond, mill in background

Photo No.21

Shad



20 Shady Lea Road North Kingstown, R.I.

Photographer: Charlene Roise

Date: July 1981

Negative filed at: R.I. Historical Preservation Commission (CKR 1:36)

Description: Rodman House, from southwest

Photo No.22

200



63-69 Shady Lea Road North Kingstown, R.I.

Photographer: Charlene Roise

Date: July 1981

Negative filed at: R.I. Historical Preservation Commission (CKR 1:32)

Description: Mill tenement, north facade

Photo No. 23

- 83

Shas



233 (right) and 234-236 (left) Shady Lea Road North Kingstown, R.I.

Photographer: Charlene Roise

Date: July 1981

Negative filed at: R.I. Historical Preservation Commission (CKR 1:31)

Description: Mill double houses from west

Photo No. 24

230-

238

Shad

600

A O



1340 Tower Hill Road North Kingstown, R.I.

Photographer: Charlene Roise

Date: July 1981

Negative filed at: R.I. Historical Preservation Commission (CKR 1:35)

Description: Potpourri Potters from northwest (formerly Rodman estate barn)

Photo No.25

ower

- Hull D