35. Organization: SHELBY CO. HIST. SOC.

Resurvey

6/1986

36. Date:

37. New Survey X

person:

1882 ATLAS OF HENRY AND SHELBY COS.,

KENTUCKY; MRS. LYLE BUCKNER

# KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource SHELBY	ŧ	SH	247
	_		County

	· · · · · · · · · · · · · · · · · · ·	
4. Diane of gesonce:	16. Date: Original Building CA 1880 Addition	[ 5 ]
SamOriginal Owners	Addition	[ - ]
3. Other Names:	FRINCESS ANNE	[ <sup>4P</sup>
4. Prehistoric Site Building Object	18. Architect/Builder:	
Historic Site Structure Other		
5. Location: EMINENCE QUAD.; E.S. KY.55, 1/2 MI.	19. No. of Stories: TWO	[2.0]
EMINENCE QUAD.; E.S. KY.55, 1/2 MI. N. OF FOX RUN RD. INTERSECTION	20. Original Floor Plan: CENTER PASSAGE, T-PLAN	[TF
6. Owner's Name: COY AND LINDA LOGAN	21. Single Pile Double Pile N.A	
IP 1	22. Roof Form & Material: Original GABLE & HIF/ ASPHALT Not Original	
7. Owner's Address: ROUTE 1 BOX 228	23. Structural Material: FRAME	[W
SHELBYVILLE, KENTUCKY 40065	24. Exterior Material:CLAFBOARD	[W
8. Evaluation: N.R. POTENTIAL [N]	PLAIN, 5", WOOD GINGERBREAD	
9. Recognition & Date:	25. Foundation Material:	_ <del></del>
Nat.Landmark Local Landmark	STONE	[s ]
Nat.Register HABS/HAER	26. Major Alterations: None	
Highway Marker KY Inventory 1986	Moved/Rebuilt Other	
KY Landmark Certificate	Additions X	
10. N.R.Status & Date:	27. Special Features:	
11. N.R.Group:	00 0 4 22	
District Name: [ ] Mult.Resource Area SHELBY COUNTY [ ]	28. Outbuildings: NONE CONTRIBUTING	[NC ]
Thematic Name:		
12. Historical Theme:	29. Original Function: RESIDENTIAL	
Primary: ARCHITECTURE [030 ]	30. Present Use:	[01A]
Secondary: [ ]	RESIDENTIAL	[01A]
Other: [ ]	31. Condition:	
13. Statement of Significance:	GOOD	[G ]
	32. Endangered: Yes	
THE GLASS HOUSE IS SIGNIFICANT	No	X
ON A LOCAL LEVEL UNDER CRITERIA	33. Attach Photos:	
C, AS A GOOD EXEMPLE OF TURN-OF- THE-CENTURY DOMESTIC FARM BUIL-	Roll Photo Nos: 7 No. of Slide	es:
DING. THE HOUSE IS AN ELABORATE	1.6	
CENTER PASSAGE T-PLAN, (CONTIN.) [C ]		
14. History:		
THE HOUSE WAS THE FARM HOUSE OF SAMUEL		
D. GLASS WHO RESIDED HERE BEFORE 1882.		
IT IS NOT KNOWN WHEN THIS HOUSE WAS CON-		
STRUCTED, BUT THE QUEEN ANNE DETAILS AND		
PLAN SUGGEST CIRCA 1880. THE ORIGINAL		
ONE AND ONE-HALF STORY LOG HOUSE THAT		
THIS BUILDING REPLACED WAS TORN DOWN		
MANY YEARS AGO. THE PROPERTY WAS OWNED		
BY THE GLASS FAMILY UNTIL VERY RECENTLY.		
THE LAST TWO SAMUEL GLASSES OPERATED A		
DIVERSIFIED FARM WITH CATTLE, HOGS AND		
SHEEP.		
15. Source of historical information and/or contact	34. Prepared by: CHRISTINE AMOS	


## KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource #

SH 247

3 <b>8.</b>	UTM Point of Primary Building: Quadrant:EMINENCE	Zone	Easting 657660	Northing 4236600	<ul><li>39. G.I.S. Mod.</li><li>40. Coordi.Accuracy</li></ul>	[ ]
11.	UTM Points of Boundary (for N. R. A. B. C.	. eligibl - -	e sites only): I E F			
12.	Total Acreage in Present Property	1: 260	43. Acre	age included in p	proposed N.R. boundary:	41

44. Site Plan (and boundary description and justification for N.R. sites):




THE PROPERTY BEING NOMINATED CONTAINS LESS THAN ONE ACRE AND IS THE YARD AREA IMMEDIATELY SURROUNDING THE FARM THERE ARE THREE BARNS, A RESIDENCE. SILO AND SEVERAL OTHER OUTBUILDINGS ASSOCIATED WITH THE FARM TO THE NORTH-EAST BUT THEY ARE NOT INCLUDED WITHIN THE BOUNDARIES BECAUSE OF LOSS OF IN-TEGRITY OR RECENT CONSTRUCTION DATES. THE DIMENSIONS OF THE PROPERTY MEASURE ROUGHLY 200' FEET SQUARE, CENTERED ON THE HOUSE AND DELINEATED ON THE SOUTH AND WEST BY A BOARD FENCE. A MOBILE HOME LOCATED WITHIN THE YARD AREA IS CONSIDERED IMPERMANENT AND THEREFORE, NOT COUNTED IN THE PROPERTY.

The southeast corner, point A, is located 75' SE of the SE corner of the house, and 100' south of the drive.

## 45. Description and House Plan:

THE PROPERTY, A TURN OF THE CENTURY, FRAME FARM HOUSE LOCATED 2/5 OF A MILE EAST OF KY. 55 AND ACCESSED BY A HALF MILE GRAVEL DRIVE, IS CENTERED JITHIN THIS 268 ACRE FARM. THE HOUSE IS A TWO STORY MODIFIED T-PLAN WITH CENTER PASSAGE, THREE DISTINCT BAYS AND A COMBINATION HIP AND GABLE ROOF ALTHOUGH THE PLAIN, 5" WEATHERBOARD WALL SURFACES AND FORM ARE VERNACULAR, THE FRONT AND WEST SIDE BABLE ENDS AND GABLED PORCH EXHIBIT THE ELABORATE ESIGN AND TEXTURED DECORATION OF HIGH STYLE QUEEN ANNE ARCHITECTURE. THE HOUSE, LOCATED AT THE END OF A LONG DRIVE, IS SURROUNDED BY THE LANDS OF THE FARM, AND AN IMMEDIATE YARD WITH MATURE MAPLES AND THE PROPERTY EXHIBITS GOOD TO EXCELLENT INTEGRITY OF DESIGN, MATERIALS, WORKMANSHIP, LOCA-TION, SETTING, FEELING AND ASSOCIATION (PHOTOS 7-7,8,9,10).

ESPITE THESE ORNATE AND SPORADIC ELEMENTS (CONT.)



Continuation Sheet SH 247
S.D. Glass house

page 3 of 3 pages

### 13. Statement of Significance, continued

with applied Queen Anne decorative features such as elaborate, barrel vaulted gable end aprons, window hoods and portico. These fashionable embellishments and the large, equally sized rooms designed on the T-plan suggest a dichotomous situation: that although popular stylistic forms were sought and applied in a variety of ways, their newness contrasts with the interior arrangement of domestic living spaces, solidly based on historic tradition and very reluctant to change. The period of significance dates to circa 1880.

### 45. Description and House Plan, continued

the basic form and certainly the plan, maintain local tradition with 18 square foot rooms linked on a simple "T", with back to back fireplaces up and down and end fireplaces on the long axis end. The interior features iron mantles and grates at each of the six fireplaces; small paned cobalt and gold glass in the paneled and carved oak entry door; reeded window and door trim with bullseye corner blocks and wood panels between the lower sash and floor. Woodwork is painted, but is possibly oak.

The east portion of the rear, one story ell is original, but to the west, the porch has been enclosed and a shed roofed bath has been added (photo 8-11). Although these changes are not integral to the original building, they do not have a significant adverse effect on the property's integrity.

The nominated area contains one contributing building.