



Broad Brook Company  
East Windsor, CT

D. Ransom Photo, 9/84  
Negative: Connecticut  
Historical Commission  
MAIN STREET DAM, VIEW  
NORTHEAST  
Photograph 1



C. W. BAILLY & Co. LITH. BOSTON.

BROAD BROOK, CONN.

Broad Brook Company

East Windsor, CT

R. Bitondi Copy, 8/84

Negative: Connecticut

Historical Society

O.H. BAILEY & CO. VIEW,

NORTHEAST

Photograph 2



AP CITY TIME  
RETREADS

Retread

Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

VIEW SOUTHEAST OF BUILDINGS

4, 3B, 2, 2A, 3A, 3

Photograph 3



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

VIEW NORTHWEST OF BUILD-

INGS 17, 11, 5A, 3E, 3, 3A

Photograph 4





Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84


Negative: Connecticut

Historical Commission

ROOF LINE OF NORTHWEST CORNER

OF BUILDING 3, VIEW SOUTHEAST

Photograph 5



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

WINDOW, BUILDING 3A, EAST

ELEVATION, THIRD FLOOR,

VIEW SOUTHEAST, TYPICAL

Photograph 6



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

BUILDING 3, FIFTH FLOOR,

VIEW NORTHEAST

Photograph 7



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut  
Historical Commission

BUILDING 3A, THIRD FLOOR

CEILING, TERMINATION OF

VERTICAL ROD, TYPICAL

Photograph 8





Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

VIEW NORTH OF BUILDINGS 29,

17, 11, 3, 3A

Photograph 9



Broad Brook Company  
East Windsor, CT

D. Ransom Photo, 9/84  
Negative: Connecticut  
Historical Commission

VIEW NORTH OF BUILDINGS  
14A, 14, 3B, 3A, 4  
Photograph 10



Broad Brook Company  
East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut  
Historical Commission

BUILDING 3B, ROOFLINE,  
VIEW WEST

Photograph 11



Broad Brook Company  
East Windsor, CT

D. Ransom Photo, 10/84

Negative: Connecticut  
Historical Commission

BUILDINGS 13A, 13B, VIEW  
SOUTHEAST

Photograph 12





Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

VIEW SOUTH OF BUILDINGS

3, 3A, 14, 13A, 13B, 26

Photograph 13



Broad Brook Company  
East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut  
Historical Commission

BUILDING 14, FIFTH FLOOR,  
VIEW SOUTHWEST

Photograph 14



Broad Brook Company  
East Windsor, CT

D. Ransom Photo, 10/84

Negative: Connecticut  
Historical Commission

VIEW NORTHEAST OF BUILD-  
INGS 26, 14A

Photograph 13



Broad Brook Company  
East Windsor, CT

D. Ransom Photo, 10/84  
NegativeL Connecticut  
Historical Commission  
BUILDING 3C, VIEW WEST  
Photograph 15A





Broad Brook Company

East Windsor, CT

D. Ransom Photo, 10/84

Negative: Connecticut

Historical Commission

BUILDING 3E, VIEW SOUTH-  
EAST

Photograph 16



Broad Brook Company  
East Windsor, CT  
D. Ransom Photo, 9/84  
Negative: Connecticut  
Historical Commission  
BUILDING 5, VIEW WEST  
Photograph 17



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

VIEW NORTH OF BUILDINGS

17, 11, 5A, 3E, 3

Photograph 18



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

BUILDING 11, VIEW NORTH

Photograph 19





Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

BUILDING 11, SECOND FLOOR,

VIEW WEST

Photograph 20



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

POWERHOUSE AND BUILDINGS

17, 17A, VIEW NORTHWEST

Photograph 21



Broad Brook Company

East Windsor, CT

D. Ransom Photo, 9/84

Negative: Connecticut

Historical Commission

BUILDINGS Y1, Y4, VIEW

SOUTHWEST

Photograph 22