



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Facade of House. Camera Facing North

1 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Facade of Log Section. Camera Facing Northwest.

2 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Facade of 1780 Stone Section. Camera Facing Northwest

3 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Rear of Building. Camera Facing Southeast.

4 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Side of 1780 Stone Section with Datestone

in Gable. Camera Facing East

50F 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Side of Building Including Log Section and Rear
Lean-to Addition. Camera Facing Southwest.

6 of 18





Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware


Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Detail of Log Facade Showing Filled-in Window and
Notches for Floor Joists. Camera Facing North.

8 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Detail of Log Facade, Camera Facing North

9 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Portion of Log Wall, Door Jamb and Sill Supported by
Stone Foundation Wall in Lean-to Section.

Camera Facing Southeast.

10 of 18



Charles Springer House and Tavern (N-507)
4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807
Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation
15 The Green

Dover, DE 19901

Boxed-In, Winder-Stair Leading to Second Floor.
in First Floor of Log Section of House.

Camera Facing East

11 of 18



C-52780

Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Detail of Datestone in Gable of 1780 Stone Section
of House. Camera Facing East.

120F 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Detail of Scars Indicating Possible Location of
Corner Cupboard or Bar. First Floor of 1780
Stone Section. Camera Facing Northwest.

13 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Square Area Indicating Location of Former Boxed-In

Winder-Stair Ceiling of Second Floor Hall of 1780

Stone Section. Camera Facing North

14 of 18



Charles Springer House and Tavern (N-507)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Anne Wilson

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Original Closet Door and Door Leading to the

Hall of the 1780 Stone Section.

Camera Facing East

15 of 18



Charles Springer House and Tavern (N-507.1- 507.12)

Moses Journey Barn (N-507.2 or N-508)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Stone Walls of 1852 Moses Journey Barn

Camera Facing Northwest

16 of 18



Ruins of Springhouse (N-507.3)

Charles Springer House and Tavern (N-507.1-507.12)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Ruins of Springhouse (N-507.3). Camera Facing
Southeast.

17 of 18



Charles Springer House and Tavern (N-507.1 - N-507.12)

Four Mile Marker (507.4)

4921 Lancaster Pike

Wilmington, Christiana Hundred, Delaware 19807

Valerie Cesna

February, 1990

State of Delaware

Bureau of Archaeology and Historic Preservation

15 The Green

Dover, DE 19901

Four Mile Marker Indicating Distance to Wilmington
Camera Facing Northeast

18 of 18