



RESIDENCE OF JOHN E. MORGAN, CORNER OF CHURCH AND JACKSON STREETS.

MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
unknown, 1887. No negative. View from
north. Photo #1 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by Edw.
Noyes, Jan. 1983. Negative at Winn. Hist.
Society. View from north. Photo #2 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, Jan. 1983. Negative at
Winn. Hist. Society. View from east.
Photo #3 of 29.




MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. Detail of tower.
Photo #4 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at Winn.
Hist. Society. View of porch from west.
Photo #5 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of porch from
east. Photo #6 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. Detail of front
porch railing. Photo #7 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of front
entrance. Photo #8 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of entrance
lock. Photo #9 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of grand
staircase. Photo #10 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of grand
staircase newel post. Photo #11 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of grand
staircase niche. Photo #12 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of fireplace,
parlor. Photo #13 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. Detail of parlor
fireplace wall. Photo #14 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of parlor
chandelier (original). Photo #15 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of built in
sideboard, dining room. Photo #16 of 29.




NEXT 2 12
VIALS NO
LOTION 01
3 4 22 1076

dry
ton

cystine-bond

MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of built in
bookcases, library. Photo #17 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of vestibule
flooring. Photo #18 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of original
Lincrusta wall covering. Photo #19 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. Detail of woodwork
and wall coving. Photo #20 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of alcove in
second floor bedroom, southwest corner.
Photo #21 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of fireplace
in second floor. Photo #22 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of second
floor hallway. Photo #23 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of transom,
second floor hallway. Photo #24 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of lavatory,
second floor bedroom. Photo #25 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of interior
wall detail of basement. Photo #26 of 29.



MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of Carriage
House. Photo #27 of 29.



STAGE

New, Chlorinated

| | |
|--------------|----|
| Directions | HY |
| INSTRUCTIONS | |

United

Sanitation

CUBITAINER

MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of original
library fixture. Photo #28 of 29.

FUTURE HOME OF...

WINNEBAGO CO.

HISTORICAL &

ARCHEOLOGICAL

SOCIETY

MORGAN, JOHN R., HOUSE. 234 Church Ave.,
Oshkosh, Winnebago County, WI. Photo by
Edw. Noyes, May 1983. Negative at
Winn. Hist. Society. View of future use.
Photo #29 of 29.