



HS-NEED-28

KIRK'S CABIN REAR

REAR N side

CANYONLANDS, NP

Location of

Photos: KIRK

S. MENZ

Date 9/81

Roll 8, #8



LOG No HS-NEED-28

Photo No _____

Subject KIRK'S CABIN/FRONT

Description of View FRONT / S. S. side
SW to NE

Location of Subject CANTONLANDS

Location of Negative RMRO

By S. Melis Date 9/86

Roll 8, #9



LOG No HS-NEED-29
Photo No _____
Subject CORRAL
GENERAL
Description of View _____
Location of Subject CANYONLANDS
Location of Negative RMRD
By S. MENZIS Date 9/46

Roll 8, #12



LCS No. NEED-30

Photo No. CARE # 14

Subject Kirk's Fence

Descrip. of View SIDE VIEW OF WOODS

Location of Subject CAMP WOODS

Location of Negative RWD-115

By S. F. Wells Date 4-28-80





LOG No HS-NEED-31

Photo No _____

Subject SECOND CORRAL

Description of View DETAIL OF FENCE
W to E

Location of Subject CANYONLANDS

Location of Negative RMRO

By S. MEHLS Date 9/86

Roll 8, #16



LCS No. NEER-31

Photo No. CNPA 11

Subject Site Second Corral

Descrip. of View Site General

Location of Subject Camp

Location of Negative 10-0-11-2

By [Signature] Date 4/22/50