

Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby, Oregon Clackamas Cty. Front (North) and East side of Church with parsonage to the right. Photographer not known Year--1918 (?) (Cannot tell

for sure from printing on picture.) Negative--John Cox, 22900 S. Penman Rd., Oregon City, Oregon 97045 Camera facing southwest

Picture #1 of 10



Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby, Oregon Clackamas Cty. Front (North) and East side of Church. New parsonage to right. At left rear, addition to the back of Church (1929) of a Sunday school room, sacresty, and altar.

Photographer not known
Photo taken in the early 1930s
Negative--Mrs. F. O. Kraxberger,
10286 S. Macksburg Rd., Canby,
Oregon 97013
Camera facing southwest

Picture #2 of 10



Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby, Oregon Clackamas Ctv. Front (North) and East side. showing Church as it appears today. Entrance changed in 1965 when Narthex was added and stairs to basement changed to make more efficient use of area. Photographer—Diane Gonthier. Canby Herald 1981 Negative--Mrs. F. O. Kraxberger, 10286 S. Macksburg Rd., Canby, Oregon 97013 Camera facing southwest

Picture #3 of 10



Macksburg Lutheran Church
10210 S. Macksburg Rd.
Canby, Oregon Clackamas Cty.
Addition at rear of Church,
made in 1929, with no other
change todate except cement
foundation.

Photographer—Diane Gonthier, Canby Herald 1981 Negative—Mrs. F. O. Kraxberger, 10286 S. Macksburg Rd., Canby Oregon 97013 Camera facing northwest

Picture #4 of 10



Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby, Oregon Clackamas Ctyl Sheep grazing in orchard which joins Church property to the East. Wheat fields in background.

Photographer—Diane Gonthier, Canby Herald 1981 Negative—Mrs. F. O. Kraxberger, 10286 S. Macksburg Rd., Canby, Oregon 97013 Camera facing southeast

Picture #5 of 10



Macksburg Lutheran Church
10210 S. Macksburg Rd.
Canby, Oregon Clackamas Cty.
New home of a grandson of a

charter member of Church. Barn and shed are original buildings on the grandparents' property which is across the road from the Church. Photographer—Diane Gonthier,

Canby Herald 1981
Negative—Mrs. F. O. Kraxberger, 10286 S. Macksburg Rd., Canby, Oregon 97013
Camera facing northeast

Picture #6 of 10



Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby. Oregon Clackamas Cty. New home and seed beds across from (north) Church. Large fields and old buildings at rear of picture. Photographer-Diane Gonthier, Canby Herald 1981 Negative--Mrs. F. O. Kraxberger, 10286 S. Macksburg Rd., Canby, Oregon 97013 Camera facing north

Picture #7 of 10



Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby, Oregon Clackamas Cty. Basement fellowship room, used for Sunday School, club meetings, flower shows, elections, wedding receptions.

Photographer—Mrs. Dave Brown, 15526 S. E. Francis Ave., Milwaukie, Oregon 97222 1981 Negative—Mrs. F. O. Kraxberger, 10286 S. Macksburg Rd., Canby, Oregon 97013 Camera facing north

Picture #8 of 10



Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby, Oregon Clackamas Cty. Pews installed, 1944. Windows replaced at same time with original casings. Plasterboard added in 1944 when original wainscoating painstakingly removed and reused. Cry Room extreme left. Photographer--Mrs. Dave Brown, 15526 S. E. Francis Ave., Milwaukie, Oregon 97222 1981 Negative--Mrs. F. O. Kraxberger, 10286 S. Macksburg Rd., Canby, Oregon 97013 Camera facing east

Picture #9 of 10



Macksburg Lutheran Church 10210 S. Macksburg Rd. Canby, Oregon Clackamas Ctv. Chapel and altar. Door to Sunday School room on right, Sacristy on left. Photographer--Mrs. Dave Brown, 15526 S. E. Francis Ave., Milwaukie, Oregon 97222 1981 Negative--Mrs. F. O. Kraxberger. 10286 S. Macksburg Rd., Canby, Oregon 97013 Camera facing south

Picture #10 of 10